JSPF) 20 holes. Acidized w/ 300	OOO gals 15% NeFe, ISIP 1000 psi. Ada TLE Petroleum Engineer DATE 11/30/90	(2
JSPF) 20 holes. Acidized w/ 300	OOO gals 15% NeFe, ISIP 1000 psi.	(2
Perforated 3290', 3302', 3330', JSPF) 20 holes. Acidized w/ 300	000 gals 15% NeFe, ISIP 1000 psi. Adm	(2
Perforated 3290', 3302', 3330', JSPF) 20 holes. Acidized w/ 300	000 gals 15% NeFe, ISIP 1000 psi.	(2
Perforated 3290', 3302', 3330', JSPF) 20 holes. Acidized w/ 300	000 gals 15% NeFe, ISIP 1000 psi.	(2
	3332', 3405', 3406', 3418', 3427', 3430', 3436'	
Perforated 3483', 3484', 3485', 3518', 3533', 3534' (2 JSPF) 28 1130 psi.	3486', 3496', 3497', 3506', 3514', 3515', 3516', holes. Acidized w/ 3000 gals 15% NeFe acid. ISI	3517 P
3682', 3690', 3697', 3718', 3719	3630', 3636', 3646', 3648', 3652', 3653', 3656', 9'. Acidized 3627'-3719' w/ 3000 gals 15% NeFe.	
3860', 3861', 3862', 3863', 3877	3796', 3822', 3823', 3855', 3856', 3857', 3858', 7', 3878', 3879', 3880', 3881', 3882', 3886', 388 ed perfs w/ 4000 gals 15% NeFe. ISIP 1050 psi.	
17. DESCRIDE PROPOSED OF COMPLETED OPERATIONS (Clearly state all proposed work. If well is directionally drilled, give subsurnent to this work.) *	Il pertinent details, and give pertinent dates, including estimated date of starting urface locations and measured and true vertical depths for all markers and sones in the control of th	any erti-
REPAIR WELL CHANGE PLANE	(Other) (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON®	FRACTURE TREATMENT ALTERING CASING XX SHOOTING OR ACIDIZING XX ABANDONMENT®	
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHUT-OFF REPAIRING WELL	
16. Check Appropriate Box To Ind	dicate Nature of Notice, Report, or Other Data subsequent Report of:	
3615.5 GR	i Eddy i NM	
14. PERMIT NO. 15. ELEVATIONS (Show w	whether DF, RT, GR, etc.) ARTESIA OFFICE Sec.3-T19S-R31E 12. COUNTY OR PARISH 18. STATE	
990' FNL & 2310' FWL	DEC 7'90	<u></u>
4. LOCATION OF WELL (Report location clearly and in accordance See also space 17 below.) At surface		
3. ADDRESS OF OPERATOR P. O. Box 2208, Roswell,	NM 88202 RECEIVED 34	
2. NAME OF OPERATOR Hondo Oil & Gas Company	AREA dall was eRS East Shugart	
WELL GAS OTHER	East Shugart Unit	
(Do not use this form for proposals to drill or to deepen Use "APPLICATION FOR PERMIT—" for	or plug back to a different reservoir. for such proposals. 100 7. UNIT AGREEMENT NAME	
SUNDRY NOTICES AND REPO	6. IF INDIAN, ALLOTTEE OR TRIBE N	ME
	1	10.
(November 1983) (Formerly 9–331) DEPARTMENT OF THE IN		0

*See Instructions on Reverse Side