

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DEC 19 1990

WELL API NO. 30-015-26498
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Winston All
8. Well No. 1
9. Pool name or Wildcat Wildcat Devonian

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITARTESIA, CITE  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471
3. Address of Operator 105 South 4th St., Artesia, New Mexico 88210	4. Well Location Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 14 Township 19S Range 24E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3657' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 10850'. Reached TD 12:00 PM 12-3-90. Ran 256 joints 7" casing set at 10850' as follows: 46 joints 7" 29# N-80, 72 joints 7" 26# N-80, 107 joints 7" 26# N-80, 28 joints 7" 26# N-80, 3 joints 7" 29# N-80, Float shoe set at 10850'. Float collar set at 10850.93'. DV tools set at 8500' and 5300'. Cemented in 3 stages. Stage 1: 500 gals Superflush 101. Tailed in with 400 sacks "H" + 5# Salt + 5# Gilsonite + 0.4% Halad 22A + 0.3% CFR3 (yield 1.31, weight 15.2). PD 12:07 AM 12-6-90 with 1800 psi. Circulated 200 sacks. Stage 2: 500 gals Superflush 101. Tailed in with 1400 sacks "H" + 5# Salt + 5# gilsonite + 0.4% CFR3 + 0.4% Halad 22A (yield 1.32, weight 15.2). PD at 4:02 AM 12-6-90 with 2750 psi. Circulated 187 sacks. Stage 3: 850 sacks "H" Lite + 5# gilsonite + 1/4# flocele (yield 2.0, weight 12.4). Tailed in with 100 sacks "H" Neat (yield 1.18, weight 15.6). PD 7:43 AM 12-6-90 with 2400 psi. Circulated 266 sacks. Woc 18 hrs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE DEC 28 1990  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: