				CIST
Form 3160-5 (June 1990) Do not use this	DEPARTMEN BUREAU OF SUNDRY NOTICES form for proposals to dr	TED STATES IT OF THE INTERIOR LAND MANAGEMENT AND REPORTS ON WELL ill or to deepen or reentry to R PERMIT—" for such propo	a different reservoir.	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC-029388- 6. If Indian, Allottee or Tribe Name
	7. If Unit or CA, Agreement Designation			
1. Type of Well Constraints of Operator Marathon Oil 3. Address and Telephone P. O. Box 555 4. Location of Well (Foo Unit J, 1980 Section 10, 12 12. CHECK	 B. Well Name and No. Stetco''10''Federal No.3 9. API Well No. 30-015-26513 i0. Field and Pool. or Exploratory Area Tamano (Bone Spring) 11. County or Parish, State Eddy County, N.M. AT, OR OTHER DATA 			
			TYPE OF ACTION	
X Notice	e of Intent quent Report Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)
give subsurface b Marathon Oil	Company proposes	the conversion of the	Marathon Stetco	"10" Federal No. 3 SC) Unit well No. 303

Marathon Oil Company proposes the conversion of the marathon offector is received in the formation of the marathon of the marathon of the formation of the marathon offector is the formation of the formation of

(see attached)

	bject	
Like	App	roval
by	Stat	le

I hereby certify that the foregoing is the	rue and correct	<u> </u>		
Signed Shuay		Tille Northwest	Production Supt	Date
(This space for Federal or State office		· · · · · · · · · · · · · · · · · · ·	*	Date 10/24/91
Approved by	· · · · · · · · · · · · · · · · · · ·			Date [0] 2=+ 7 51

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

Form 3160-5 Stetco "10" Federal No. 3

- 1. MIRU PU. Kill well w/2% KCL water if necessary.
- 2. Nipple down well head & nipple up BOP.
- 3. Release TAC and POOH laying down 2 3/8" production string.
- 4. Pickup up 5 1/2" RTTS tool, seating nipple and RIH on 2 7/8" workstring. Set packer at 7900'.
- 5. Acidize Bone Spring Second Carbonate perfs 8030' to 8096' with 500 gals of 15% HCL.
- 6. Swab back load.
- 7. Unset packer. POOH laying down workstring and packer.
- 8. Pick up a wireline re-entry guide (IPC & EPC), 2 3/8" x 5 1/2" Baker Lok-Set (EPC and internally lined w/fiberglass) or equivalent, on-off tool (EPC w/1.50" 316 stainless steel profile) on 2 3/8" internally fiberglass lined injection tubing. Set packer at 7950'.
- 9. Release on-off tool and reverse circulate 2% KCL w/1 bbl of packer fluid down backside (est.116 bbls). Latch onto on-off tool.
- 10. Nipple down BOP and install well head.
- 11. Conduct mechanical integrity test on backside for one hour.
- 12. RDMO PU.
- 13. Connect well to injection system and commence injection into Second Bone Spring Carbonate.
- 14. After approximately two weeks of injection, rig up loggers and conduct injection profile survey.

This work is scheduled to commence during the month of December, 1991.