Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

CONDITIONS OF AFTROVAL, IF ANY:

Form C-103
Revised 1-1-89

DISTRICT II P.O. Drawer DD, Artesia, NM 88210		P.O. Box 2088 Santa Fe, New Mexico 8750			WELL API NO. 30-015-26521 5. Indicate Type of Lease		
				JAN 17 '91	NM-468		
SUNDRY NOTICES AND REPORTS ON WI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE			OR TO DEEPEN	OR PLUG BACKETS A	7 Jassa Nama o	or Unit Agreement Nam	
[DIFFERENT RESERV	/OIR. USE "APPLIC 01) FOR SUCH PRO	ATION FOR PE	AMIT" ARTESIA, OFFICE	State	_	•
1. Type of Well: OIL WELL X	GAS WELL	o	THER		Beace	-	
2. Name of Operator					8. Well No.	_	-
ARCO OIL A 3. Address of Operat	AND GAS COMPA tor	.N Y			9. Pool name or	•	
P. O. Box	1610, Midlar	d, Texas 79	9702		Shugart	Y-SR-Q-G	
Unit Letter	N : 660	Feet From The	South	Line and165	O Feet Fro	m The West	Line
Section	2	Township 19			NMPM Edd	dy	County
		/////	00 (Show whether 418.9	DF, RKB, RT, GR, etc.)			
11.	Check A			Nature of Notice, Re	eport, or Othe	er Data	
NC	OTICE OF INT				•	REPORT OF:	
PERFORM REMEDIA	AL WORK	PLUG AND AB	ANDON	REMEDIAL WORK		ALTERING CASING	3 <u> </u>
		I LOU AND AD					
TEMPORARILY ABA		CHANGE PLAN	vs 🗍	COMMENCE DRILLING	OPNS.	PLUG AND ABANI	ONMENT _
TEMPORARILY ABA	NDON		vs			PLUG AND ABAND	OONMENT _
	NDON		vs	COMMENCE DRILLING CASING TEST AND CE OTHER: COMple	MENT JOB	PLUG AND ABAND	ONMENT X
PULL OR ALTER CA	INDON	CHANGE PLAN		CASING TEST AND CE	tion		[x
PULL OR ALTER CA	ASING	CHANGE PLAN		CASING TEST AND CE	tion		[x
PULL OR ALTER CA OTHER: 12. Describe Proposed	d or Completed Operation E 1103. RUCU. Tag Press tes gals & 63	CHANGE PLAN TD at 315 t csg to 1	4. Perf 000#. Ac	CASING TEST AND CE OTHER: comple In give pertinent dates, include Queen f/2921— idize w/2000 swab test. Ra	tion ting estimated date 2958. Set gals. Fra	of starting any proposed t pkr at 27 ac w/25,000	<u>x</u>
PULL OR ALTER CA OTHER: 12. Describe Proposed work) SEE RULE 11-30-90.	d or Completed Operation E 1103. RUCU. Tag Press tes gals & 63	TD at 315 t csg to 1,000 # sd. s & pmp. R	4. Perf 000#. Ac co sd &	CASING TEST AND CE OTHER: comple In give pertinent dates, include Queen f/2921- idize w/2000 swab test. Ra -90.	tion ting estimated date 2958. Set gals. Fra	of starting any proposed t pkr at 27 ac w/25,000	<u>x</u>
PULL OR ALTER CA OTHER: 12. Describe Proposed work) SEE RULE 11-30-90.	d or Completed Operation E 1103. RUCU. Tag Press tes gals & 63 2999, rod	TD at 315 t csg to 1,000 # sd. s & pmp. R	4. Perf 000#. Ac co sd &	CASING TEST AND CE OTHER: comple In give pertinent dates, include Queen f/2921- idize w/2000 swab test. Ra -90.	tion ting estimated date 2958. Set gals. Fra	of starting any proposed t pkr at 27 ac w/25,000	<u>x</u>
PULL OR ALTER CA OTHER: 12. Describe Proposed work) SEE RULE 11-30-90.	d or Completed Operation E 1103. RUCU. Tag Press tes gals & 63 2999, rod	TD at 315 t csg to 1,000 # sd. s & pmp. R	4. Perf 000#. Ac co sd &	CASING TEST AND CE OTHER: comple In give pertinent dates, include Queen f/2921- idize w/2000 swab test. Ra -90.	tion ting estimated date 2958. Set gals. Fra	of starting any proposed t pkr at 27 ac w/25,000	<u>x</u>
PULL OR ALTER CA OTHER: 12 Describe Proposed work) SEE RULE 11-30-90. 01-13-91.	d or Completed Operation 1103. RUCU. Tag Press tes gals & 63 2999, rod In 24 hrs	TD at 315 t csg to 1,000# sd. s & pmp. R pmpd 34 E	A. Perf 000#. Ac co sd & DPU 12-7	CASING TEST AND CE OTHER: comple Indigive pertinent dates, included a give pertinent dates, includ	tion tion ting estimated date 2958. Set gals. Frain CA: 2-	of starting any proposed t pkr at 27 ac w/25,000 -3/8 tbg to	(60.
PULL OR ALTER CA OTHER: 12. Describe Proposed work) SEE RULE 11-30-90. 01-13-91. I hereby certify that the SIGNATURE	d or Completed Operation 1103. RUCU. Tag Press tes gals & 63 2999, rod In 24 hrs	TD at 315 t csg to 1,000 # sd. s & pmp. R pmpd 34 B	A. Perf 000#. Ac co sd & DPU 12-7	CASING TEST AND CE OTHER: comple Indigive pertinent dates, included give pertinent given give	tion tion 2958. Set gals. Fran CA: 2-	of starting any proposed t pkr at 27 ac w/25,000 -3/8 tbg to	(60.
PULL OR ALTER CA OTHER: 12. Describe Proposed work) SEE RULE 11-30-90. 01-13-91. I hereby certify that the SIGNATURE	d or Completed Operation 1103. RUCU. Tag Press tes gals & 63 2999, rod In 24 hrs	TD at 315 t csg to 1,000 # sd. s & pmp. R pmpd 34 B	A. Perf 000#. Ac co sd & DPU 12-7	CASING TEST AND CE OTHER: comple Indigive pertinent dates, included give pertinent given give	tion tion ting estimated date 2958. Set gals. Frain CA: 2-	of starting any proposed t pkr at 27 ac w/25,000 -3/8 tbg to	(60.
PULL OR ALTER CA OTHER: 12. Describe Proposed work) SEE RULE 11-30-90. 01-13-91. I hereby certify that the SIGNATURE	ANDON SING SING SING SING SING SING SING SIN	TD at 315 t csg to 1,000 # sd. s & pmp. R pmpd 34 E	A. Perf 000#. Ac co sd & DPU 12-7	CASING TEST AND CE OTHER: comple Indigive pertinent dates, included give pertinent given give	tion tion 2958. Set gals. Fran CA: 2-	t pkr at 27 ac w/25,000-3/8 tbg to	(60. 5/91
PULL OR ALTER CA OTHER: 12 Describe Proposed work) SEE RULE 11-30-90. 01-13-91. I hereby certify that the SIGNATURE TYPE OR FRINT NAME	ANDON SING SING SING SING SING SING SING SIN	TD at 315 t csg to 1,000 # sd. s & pmp. R pmpd 34 E	periment details, and 4. Perf 000#. Ac co sd & 2DPU 12-7 30, 41 BW	CASING TEST AND CE OTHER: comple Indigive pertinent dates, included give pertinent given give	tion tion 2958. Set gals. Fran CA: 2-	t pkr at 27 ac w/25,000-3/8 tbg to	(60.