Form 3160-5		CONTACT RECEIV / OFFICE FOR NUMBER OF COPIES REQUIRED	Modif NM06	Roswell District ied Form No. 0-3160-4	C
E_{0}	TMENT OF THE INTERIOF AU OF LAND MANAGEMENT	INTERIOR (Other instructions on reverse side)		5. LEASE DESIGNATION AND SERIAL NO. NM-87985 29228	
SUNDRY NO	TICES AND REPORTS (ON WELLS	6. IF INDIAN	, ALLOTTEE OR TRIBE	NAME
(Do not use this form for propo	osals to drill or to deepen or plug back ATION FOR PERMIT-" for such proposals.	to a different reservoir.			
	1	EFR 1 5 1001	7. UNIT AGR	EEMENT NAME	
NAME OF OPERATOR			-	LEASE NAME	
Meridian Oil Inc.		<u>O. C. D.</u>		"3" Federal	
ADDRESS OF OPERATOR		3a. AFARTESTAPHOTOPE	9. WELL NO	J.	
21 Desta Dr., Midland,		915-686-5600		ND POOL, OR WILDCAT	
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 			Shugart (Y, SR, Q, G)		
At surface 2310' F\$L & 1650'FEL	(575)		11. SEC., T.,	R., M., OR BLK. AND	
			SURVI	EY OR AREA	
N				T19S, R30E	
4. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY		TATE
30-015-26597	3439' GR.		Eddy	NM	
6. Check	Appropriate Box To Indicat	te Nature of Notice, Rep	port, or Othe	r Data	
NOTICE OF INTE	INTION TO:	SUBS	EQUENT REPORT OF:		
			<u> </u>	EPAIRING WELL	[]
		WATER SHUT-OFF		LTERING CASING	┝━━┥
	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING		BANDONMENT*	
SHOOT OR ACIDIZE		(Other) Set & Cmt C			x
			its of multiple con	npletion on Well	
posed work. If well is direction work.)* 1/23/91Spud well. Set	D OPERATIONS (Clearly state all pertinent nally drilled, give subsurface locations 8–5/8" csg @485'. Cmt w/	Completion or Rec details, and give pertinent dates, and measured and true vertical dep	including estimated oths for all markers	d date of starting a s and zones pertine	THE TO THIS
(Other) 7. DESCRIBE PROPOSED OR COMPLETED posed work. If well is direction work.)* 1/23/91Spud well. Set 2% CaCl2.	nally drilled, give subsurface locations a	details, and give pertinent dates, and measured and true vertical dep '150 sx Ht 12% Thixad +	including estimate pths for all marker 10# Hyseal	d date of starting a s and zones pertine	THE TO THIS
(Other) 7. DESCRIBE PROPOSED OR COMPLETED posed work. If well is direction work.)* 1/23/91Spud well. Set 2% CaCl2.	Ally drilled, give subsurface locations a 8-5/8" csg @485'. Cmt w/ @3500'. Cmt w/460 sx Cla /91 circulated 156 sacks	details, and give pertinent dates, and measured and true vertical dep '150 sx Ht 12% Thixad +	Including estimate pths for all markers 10# Hyseal of ass C Neat. C	d date of starting a s and zones pertine & 310 sx-Clas 05 February	
(Other) 7. DESCRIBE PROPOSED OR COMPLETED posed work. If well is direction work.)* 1/23/91Spud well. Set 2% CaCl2. 1/29/91Set 5-1/2" csg Plug down @9:25 PM 1/31, 18. I hereby certify that the foregoing SIGNED	Ally drilled, give subsurface locations a 8-5/8" csg @485'. Cmt w/ @3500'. Cmt w/460 sx Cla /91 circulated 156 sacks /91 circulated 156 sacks /91 circulated 156 sacks /91 circulated 156 sacks	<u>i</u> <u>completion or Rec</u> details, and give pertinent dates, and measured and true vertical dep 150 sx Ht 12% Thixad + ass C tailed w/500 sx Cla	Including estimate pths for all markers 10# Hyseal of ass C Neat. C	d date of starting a s and zones pertine & 310 sx-Clas 05 February	

.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.