## to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
<b>Revised 1-1-89</b>

DIGHTICTI			
DISTRICT I			
P.O. Por 1090	Unhha	NM	222 <i>40</i>

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

WELL API NO.

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088 RECEIVED		30-015-26670
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease
DISTRICT III	•	10 F v 3 (3)	1
1000 Rio Brazos Rd., Aztec, NM 87410		O. C. D.	6. State Oil & Gas Lease No.
SUNDRY NOTICES A	AND REPORTS ON WEL	LS	
( DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. (FORM C-101) FO	LS TO DRILL OR TO DEEPEN USE "APPLICATION FOR PEF OR SUCH PROPOSALS.)	OR PLUG BACK TO A RMIT"	7. Lease Name or Unit Agreement Name
I. Type of Weil: OIL GAS WELL XX WELL	OTHER		Clifford ADD
2. Name of Operator YATES PETROLEUM CORPORATION	1		8. Weil No. 2
3. Address of Operator			9. Pool name or Wildcat
105 South 4th St., Artesia,	, NM 88210		North Dagger Draw U/Penn
4. Well Location	Cou+h	660	Fast
Unit Letter :1980 For	et From The	Line and	Feet From The East Line
sociae 35 To	wnship 19S Ra	24E	NMPM Eddy County
Section To	10. Elevation (Show whether		
	3652'	GR	<u> </u>
11. Check Appro	priate Box to Indicate 1	Nature of Notice, Re	eport, or Other Data
NOTICE OF INTENT			SEQUENT REPORT OF:
	LUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	HANGE PLANS	COMMENCE DRILLING	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	
OTHER:		OTHER: Set produ	uction csg, perforate, treat X
Stage 1: 1000 g. Superflush 4/10% Halad 22A, 7/10% CFR-3 4 hrs. Opened tool w/500#. "C", 1/4#/sx Flocele, 5# Gil 1/4# Flocele (yield 1.30, wt WOCU 24 hrs. Drilled out DV	1. Ran 198 jts 7", float collar set 102, followed w/7 (yield 1.30, wt 1 Circ 30 sacks. Bu sonite (yield 1.92 15.2). PD 10:45 tool. Perforated 719, 21, 23, 25, 27	23# and 26# N-8106'. DV too. 25 sx Premium P. 5.2). PD 4:30 Amped plug to 186 , wt 12.4). Ta: AM 7-20-91. Ci: 7698-7753' w/33, 29, 31' (14 ho	-80 and J-55 LT&C casing set 1 set 5611'. Cmt'd in 2 stages. 1us "H", 5#/salt, 10# Gilsonite, AM 7-20-91 Circ. thru DV tool 100#. Stage 2: 600 sx Howco Lite 11 in w/475 sx "H" w/5# Gilsonite 12 c 218 sacks. Close tool w/3000# 1250" holes as follows: 7698, 1501es-2 SPF), 7743, 45, 47, 49, 51

I hereby certify that the infor	mation above is true and complete to the best of my know	wenge and benea.	
SIGNATURE CA	nte Dodditt	muz Production Supervisor	DATE
TYPBOR PRINT NAME	Juanita Goodlett		<b>ТЕГЕРНОИЕ NO.</b> 505/748-1471
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS		0 1001
APPROVED BY	SUPERVISOR, DISTRICT IT	тте	DATE JUL 2 9 1991