Submit 3 Copies to Appropriate District Office

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

State of New Mexico Energy, minerals and Natural Resources Department

Form C-103	
Revised 1-1-89	

FEE X

OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

roum C-100
Revised 1-1-89

STATE

WELL API NO.

30-015-26670

5. Indicate Type of Lease

1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreemen	nt Name
1. Type of Well: OIL GAS WELL X WELL OTHER	WORKO	Haven	Clifford ADD	
2. Name of Operator		<u> </u>	8. Well No.	
YATES PETROLEUM CORPORATION	iΩù	- 8 1991	2	
3. Address of Operator		0 100	9. Pool name or Wildcat	I/Dame
105 South 4th St., Artesia, NM 88210). C. D.	North Dagger Draw U	J/Penn
4. Well Location		SIA OFFICE	_ F:	ast line
Unit Letter I: 1980 Feet From The Sou	th	Line and660	Feet From The	Line Line
. 35 Tourship 19S	Ra	nge 24E	NMPM Eddy	County
Section (Sh	ow whether i	DF, RKB, RT, GR, etc.)		
/////////	3652' GF		<i></i>	
11. Check Appropriate Box to I	Indicate N	Nature of Notice, F	Report, or Other Data	
NOTICE OF INTENTION TO:		SUF	BSEQUENT REPORT	OF:
NOTICE OF INTENTION TO.				
PERFORM REMEDIAL WORK PLUG AND ABANDO	ON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON CHANGE PLANS		COMMENCE DRILLIN	IG OPNS. PLUG AND	ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND C		
AT150.		OTHER: Squeeze	existing perfs, per	forated X
OTHER:		l treated		
12. Describe Proposed or Completed Operations (Clearly state all pertine	ens desails, ar	nd give pertinent dates, incl	uding estimated date of starting any	proposed
work) SEE RULE 1103. 9-24-91. Set EZ drill retainer at 76. Pump 100 sx "H" Neat and 200 sx "H" we stung out of retainer and reversed exception below retainer. Test squeeze interval holes as follows: 7816, 20, 23, 25, w/1500 g. 15% NEFE acid. Swabbed well 10-1-91. Set EZ drill retainer at 78. Pressure annulus to 400 psi. Pumped 2 perfs 7816-37' to 3000 psi. Stung ou Made 6 - 10' pentrations at following pentration holes 7760-7765' w/10000 g	70'. E. /4/10% cess ce 1 to 12 30, 32, - all 00'. E 5 sx Cl t of re depths	stablish injectors of the stablish injectors	tion rate of 2 BPM @ ed perfs 7698-7753' illed out retainer a erforated 7816-7837' (2 SPF). Acidize pe tion rate of 2 BPM @ sx Class "H" Neat. erse excess cement of	to 3000 psi. to 3000 psi. and 91' of ceme w/16 .42" erfs 7816-37' d 1650 psi Squeezed out of tubing.

Returned well	to production 10-10-91.		
t 1, - =	usion have a rise and complete to the best of my kno	wiedge majoula. Production Supervisor	2072 11-7-91
TYPE OF PRINT NAME	Juanita Goodlett		TELEPHONE NO. 303/743
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS		NOV 2 1 1991
	SUPERVISOR, DISTRICT IL	TILE	DAIE

CONDITIONS OF AFPROVAL, IF ANY COMMENT OF THE PROPERTY OF THE