DISTRICT I OIL CONSERVATION DIVISION Well API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-015-26674 DISTRICT II Santa Fe, New Mexico 87504-2088 30-015-26674 P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088 State Type of Lease DISTRICT III Sundar Fe, New Mexico 87504-2088 State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 6. State Oil & Gas Lease No. (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 7. Lease Name or Unit Agreement Name		Ener Ainerals and Natural Re	sources Department	_• •	Revised 1-1-89
Differentiation 6. Same OL & Gar Lase No. Differentiation SUNDER NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FOR HOR PROCOSALS TO DRILL OR TO DEEPEN OR PLUB BACK TOAL 7. Lase Name or Unit Agreement Name 0 NOT USE THIS FOR HOR PROCOSALS TO DRILL OR TO DEEPEN OR PLUB BACK TOAL 7. Lase Name or Unit Agreement Name 1. Type of Well: Well One one Perform The Second Seco	DISTRICT I P.O. Box 1980, Hobbs, NM 88240	P.O. Box 208 Santa Fe, New Mexico	8	30-015-260 5. Indicate Type of Lease	
(DO NOT USE THIS FORM FOR PRODUCTING 10 PERFERENCE () List full of Use of Section () () PERFERENT PERFORM USE PROVENUE () () PERFERENT PERFORM USE PERFO	DISTRICT III			6. State Oil & Gas Lease N	
2. Name of Operator YATSS PETROLEUN CORPORATION Image: Comparison of the state of the sta	(DO NOT USE THIS FORM FOR	PROPOSALS TO DRILL OF TO DEEPEN	RMIT	-	eement Name
2. Name of Operator 1 MATES PEROLEUM CORPORATION 1 13. Additions of Operator 105 South 4th St., Artesia, NM 88210 1 14. Well Leader 1 990 Feet From The South Old North Dagger Draw Upper Penn. 4. Well Leader 1 990 Feet From The South Old North Program 20 Comparing 105 Socies 20 Township 195 Rame 25E NMPM Eddy Comparing 10. Elevation (Show whather DF, RAKR, RI, CR, cc.) 1 Comparing Eddy Comparing 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 1 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Alterniva casing Comparing any proposed Voot Alter Casing OTHER: Add perforations & acidize Comparing any proposed vort SET RUE 103. Check dup tubing and set in slips. Try to unscrew tubing hanger. Tubing Cold and set of proposed 10. Describe Proposed or Completed Operations (Clearly state all perioent data), and give perioent data, including estimated date of suring any proposed vort SET RUE 103.			ECEIVE	Patriot A	12 Com
3. Adding of Operator 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 4. Weil Localoo 4. Weil Localoo 990 Fee From The SouthOll CON_a, Diversity and the second	YATES PETROLEUM COR	PORATION		· 1	
Unit Hada Difference Difference Difference County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 3537' GR County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 3537' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDON IV. Describe Proposed or Completed Operations (Clearly state all perison dialit, and give periment diale, including estimated date of staring any proposed XX 12. Describe Proposed or Completed Operations (Clearly state all perison dialit, and give periment diales, including estimated date of staring any proposed XX 2-14-95 - Moved in and rigged up pulling wurit. Unseat pump and TOOH with rods. Bled Sled off casing. Picked up tubing and set in slips. Try to unscrew tubing hanger. Tubing Collars and 10 joints of 1-1/2" diptube. Rigged up rotary wireline. TH with 5-1/2" overshot with 2-1/2" grapple, 4-3/4" jars, 4-3/4" bumper sub Slod down fish, drill collars and 10 joints of 1-1/2" diptube. Rigged up TOHE and 1aid down fish, drill collars and 10 joints of 1-1/2" diptube. Rigged up Tubing anchor. TOH and 1aid down fish, drill collars	105 South 4th St., 4. Well Location	and South	CON. D	North Dagger D	
NOTICE OF INTENTION TO: SUBSEQUENT ALL OTTECT. PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER:	Unit Letter : -	Township 19S R 10. Elevation (Show whether 353)	DIS	NMPM Eddy	County
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COTHER: OTHER: OTHER: OTHER: CASING TEST AND CEMENT JOB 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RUEE 1103. OTHER: Add perforations & acidize XX 2-14-95 - Moved in and rigged up pulling vunit. Unseat pump and TOOH with rods. Bled Bled off casing. Picked up tubing and set in slips. Try to unscrew tubing hanger. Tubing collapsed and split in air slips. Could not get spear thru collapse. Rigged up rotary wireline. TIH with 2-1/8" OD chemical cutter. Cut tubing at 7468'. Tubing free. Nippled up BOP. TOOH with tubing. Latched onto fish. Released tubing anchor. 2-15-95 - TIH with 5-1/2" overshot with 2-1/2" grapple, 4-3/4" jars, 4-3/4" bumper sub and 2 4-3/4" drill collars on 2-7/8" tubing. Latched onto fish. Released tubing anchor. TOOH and laid down fish, drill collars. Shut down. Rigged up Nite as follows: 7641, 43 & 7645' (6 holes) and 7707, 08 & 7709' (6 holes). Rigged down wireline. TIH with packer and RBP		eck Appropriate Box to Indicate	Nature of Notice, F	Report, or Other Data BSEQUENT REPO	RT OF:
 work) SEE RULE 1103. 2-14-95 - Moved in and rigged up pulling unit. Unseat pump and TOOH with rods. Bled off casing. Picked up tubing and set in slips. Try to unscrew tubing hanger. Tubing collapsed and split in air slips. Could not get spear thru collapse. Rigged up rotary wireline. TIH with 2-1/8" OD chemical cutter. Cut tubing at 7468'. Tubing free. Nippled up BOP. TOOH with tubing. 2-15-95 - TIH with 5-1/2" overshot with 2-1/2" grapple, 4-3/4" jars, 4-3/4" bumper sub and 2 4-3/4" drill collars on 2-7/8" tubing. Latched onto fish. Released tubing anchor. TOOH and laid down fish, drill collars and 10 joints of 1-1/2" diptube. Rigged up wireline. TIH with 4" casing gun and perforated 7641-7709' w/12 .42" holes as follows: 7641, 43 & 7645' (6 holes) and 7707, 08 & 7709' (6 holes). Rigged down wireline. TIH with packer and RBP and 40 stands. Shut down. 2-16-95 - TIH with remainder of tubing. Set RBP at 7740'. Set packer at 7680'. Loaded hole and spotted acid. Broke perforations. Acidized perforations 7707-7709' w/2000 gallons 20% NEFE acid. Moved tools and tested RBP to 1500 psi. CONTINUED Iherby certify that the information above is take and complete to the best of my knowledge and belie. SUONATURE Rusty Klein Type Rusty Klein Type Rusty Klein The Production Clerk Date 2-23-95 	PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	COMMENCE DRILLIN CASING TEST AND C OTHER: Add pe	IG OPNS. CEMENT JOB PLUG Prforations & aci	AND ABANDONMENT
I hereby certify that the information above is trade and complete to the best of my hourses and complete	work) SEE RULE HUS. 2-14-95 - Moved i off casing. Pick collapsed and spl wireline. TIH wi Nippled up BOP. 2-15-95 - TIH with and 2 4-3/4" dril TOOH and laid dow wireline. TIH wi 7641, 43 & 7645' TIH with packer a 2-16-95 - TIH wi Loaded hole and	n and rigged up pulling w ed up tubing and set in a it in air slips. Could r th 2-1/8" OD chemical cut TOOH with tubing. h 5-1/2" overshot with 2- l collars on 2-7/8" tubin m fish, drill collars and th 4" casing gun and per (6 holes) and 7707, 08 & and RBP and 40 stands. S th remainder of tubing. spotted acid. Broke perf ON NEEF acid. Moved tool	nit. Unseat pust of get spear the ter. Cut tubin -1/2" grapple, Ang. Latched on d 10 joints of forated 7641-77 7709' (6 holes hut down. Set RBP at 7740 orations. Acid s and tested RB	imp and TOOH with inscrew tubing ha nru collapse. Ri ng at 7468'. Tub 4-3/4" jars, 4-3/ to fish. Release 1-1/2" diptube. 09' w/12 .42" ho). Rigged down w '. Set packer a ized perforation	rods. Bled inger. Tubing gged up rotary oing free. 4" bumper sub ed tubing anchor. Rigged up les as follows: wireline. t 7680'. s 7707-7709'
TYPE OR PRINT NAME Rusty Klein	I hereby certify that the information a	the second accomplate to the nest of the second		n Clerk	DATE2-23-95
(This space for State Use) ORIGINAL SECTOR W GUESS	l U Busty	Klein			<u>пеlерноме но. 505/748-1</u> 4
	(This space for State Use)	MAL BORNED RY THE W GUES			MAR 2 3 1995

CONDITIONS OF APPROVAL, IF ANY: