

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088  
RECEIVED

SEP 29 1992

WELL API NO. 30-015-26732
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-10083
7. Lease Name or Unit Agreement Name Royal A
8. Well No. 2
9. Pool name or Wildcat Undesignated (Atoka)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3451' GL; 3463' KB

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
Phillips Petroleum Company

3. Address of Operator  
4001 Penbrook Street, Odessa, Texas 79762

4. Well Location  
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line  
Section 16 Township 20-S Range 25-E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Set CIBP & temporary abandon <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-4-92: RU & pump 30 bbls 2% KCl FW. ND wellhead & NU BOP. Release pkr & POOH w/2-7/8" tbq. GIH w/CIBP on 2-7/8" tbq & set 8937' RKB. Circ. hole w/ 212 BBO 2% KCl FW w/KW137 & test csg & CIBP to 500 psi - OK.

9-5-92: POOH & LD 272 jts 2-7/8" N-80 workstring. ND BOP & NU wellhead & temporary abandoned until further evaluation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supervisor, Reg. Affairs DATE 9/28/92  
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915/368-1488

(This space for State Use)

SUPERVISOR, DISTRICT II

OCT 3 1992

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: