

dst  
dp

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

AUG 24 1992

O. C. D.

WELL API NO. 30-015-26746
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  John AGU
8. Well No. 4
9. Pool name or Wildcat South Dagger Draw U/Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3610' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line Section 14 Township 20S Range 24E NMPM Eddy County
---

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-18-92. TOH. TIH w/packer and bridge plug. Set bridge plug 7798' and packer @ 7733'. Pumped 1000gals Gypsol. Flushed 42 bbls 2% KCL. Moved bridge plug to 7733'. Set packer @ 7668'. Pumped 1000gals Gypsol. Flushed w/42 bbls 2% KCL. Shut well in 36 hrs.

8-20-92. Set bridge plug at 7798'. Set packer at 7668'. Swabbed back. Pumped 3500 gals 20% SWIC acid dropping 2 balls every 270 gals. Flushed w/66 bbls 2% KCL. Moved packer to 7668' and bridge plug @ 7733'. Pumped 2000 gals 20% SWIC acid, dropping 2 balls every 280 gals. Flushed with 58 bbls 2% KCL. Swabbed. POOH with packer and bridge plug. Hung well on pump and returned well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 8-21-92

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY MIKE WILLIAMS TITLE SUPERVISOR, DISTRICT II DATE 8-21-1992

CONDITIONS OF APPROVAL, IF ANY: