

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

MAR 16 1992

WELL API NO.  
30-015-26821

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS. C. D.  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
YATES PETROLEUM CORPORATION (505) 748-1471

3. Address of Operator  
105 South 4th St., Artesia, New Mexico 88210

4. Well Location  
Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line  
Section 29 Township 19S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3534' GR

7. Lease Name or Unit Agreement Name

Voight AJD Com

8. Well No.  
1

9. Pool name or Wildcat  
North Dagger Draw U/Penn

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-10-92. Killed well. WIH w/RBP and packer. Set RBP, tested to 2000 psi. Straddled perfs 7758-7772'. Pressured to 3000#, would not break. Straddled perfs 7718-30'. Pressured to 3000#, would not break. Straddled perfs 7654-7694'. Pumped into. Tested casing side to 1000#. Held OK. POH w/RBP and packer. Reperforated 7758-7772' and 7718-7730'. POH. WIH w/RBP and packer. Set RBP, tested to 2000#. Straddled 7758-7772'. Broke at 2800#. Treated w/6000 gals 20% NEFE acid. No communication. Moved RBP and packer, tested RBP. Straddled perfs 7718-7730'. Broke at 2600#. Treated w/9912 gals 20% NEFE acid. Moved packer above zone 7654-7694', treated w/26088 gals 20% NEFE acid. Swabbed to recover load. Work completed 3-11-92. Released to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-13-92  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS

APPROVED BY SUPERVISOR DISTRICT II TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 27 1992