Submit 3 Copies to Appropriate District Office

State of New Mexico nerals and Natural Resources Department Energy.

Form	C	-10	ß
Revis	ed	1-	1-8

PLUG AND ABANDONMENT

ита C-103 evised 1-1-89	clsf
----------------------------	------

P.O. Box 1980, Hoobs, NM 88240

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER:

P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 2750477289

WELL API NO.		
30-015-2682	27	
5. Indicate Type of I	STATE	FEE X
6 Steen Oil & Gas I	esse No	

							-
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	[4]	ov 1 1 199]	6. State	Oil & Gas Lease No).	
		D. C. D.		//////			
SUNDRY NOTICES AND REPORT	S ON MEL	SHE SIA _ DEFIC	f.				m
			IUA,	7. Leas	e Name or Unit Agre	ement Name	
DIFFERENT RESERVOIR. USE "APPLICATI	ON FOR PER	MIT"					
(FORM C-101) FOR SUCH PROPO	SALS.)			Di-	cushion AHN		
				Pine	Cushijh Am		
1. Type of Weil:	_						
OIL GAS WELL OTHE	R						
2. Name of Operator				8. Weil	No.		
YATES PETROLEUM CORPORATION				3 _			
				9. Pooi	name or Wildcat		
3. Address of Operator	`				Dagger Draw	√ U/Penn	
105 South 4th St., Artesia, NM 88210	<i>i</i>			NOLCII	Dagger Dru.		
4 Well Location					τ.	Jose	
Unit Letter N : 660 Feet From The S	outh	Line and	1980		Feet From The	west	Line
Unit Letter : Feet From the							
100	_	nge 25E		NIA CORA	Eddy		County
Section 30 Township 19S	Ran	nge ZJE		NMIPM	11111	77777777	7/////
7/////////////////////////////////////	Show whether i	DF, RKB, RT, GR.	eic.j				
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	54' GR				<u> </u>		
		James of No	tice P	enort (or Other Data		
Check Appropriate Box to) indicate I	varure or tho	uco, N	COOLS, (~~~	
11. Check repropried 2 of the Check repropri			SUB	SEQL	IENT REPOF	KI OF:	
NOTICE OF INTENTION TO:							_
		REMEDIAL WO	OBK .		ALTERI	NG CASING	L
PERFORM REMEDIAL WORK PLUG AND ABAN	DON	UCMEDIAL IN	J. u \				

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

CHANGE PLANS

Spudded 26" hole 2:40 PM 10-17-91. Set 40' fo 20" conductor. Notified Mike Stubblefield, NMOCD, Artesia, NM, of spud. Resumed drilling 14-3/4" hole 3:30 PM 10-25-91. Notified John Robinson, NMOCD, Artesia, NM. Ran 26 joints 9-5/8" 36# J-55 casing set 1129'. Guide shoe set 1129', insert float set 1085'. Cmt'd with 700 sx Pacesetter Lite w/10#/sx Gilsonite + 1/2#/sx Celloseal + 3% CaCl2 (yield 1.98, wt 12.6). Tailed in w/200 sx Class "C" + 2% CaCl2 (yield 1.32, wt 14.8). PD 12:00 PM 10-27-91. Bumped plug to 1000 psi, released pressure and float held OK. Circulated 100 sacks. WOC. Drilled out 9:00 AM 10-28-91. WOC 21 hrs. NU and tested to 1000 psi for 30 mins, OK. Reduced hole to 8-3/4". Resumed drilling.

OTHER:

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

IED BY S DISTRICT IT TITLE DATE
ett
TELEPHONE NO. 505/748-14
Production Supervisor DATE 11-7-91
to the best of my knowledge and belief.