

+
clsf
sp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY - 7 1992

O. C. D.

FIELD OFFICE

WELL API NO. 30-015-26914
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Foster AN
8. Well No. 3
9. Pool name or Wildcat North Dagger Draw U/Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION ✓
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>1</u> Township <u>20S</u> Range <u>24E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3582' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Production Casing</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8264'. Reached TD 4-29-92. Ran 199 joints 7" 23# and 26# J-55 and N-80 casing set at 8264'. Float shoe set 8264', float collar set 8222'. DV tool set 5591'. Cemented in 2 stages. Stage 1: 700 sx Class "H" + 5# CSE + 6.5/10% CF-14 + 10# Gilsonite + 1/2# Celloseal (yield 1.31, wt 15.1). PD 7:15 AM 5-1-92. Circulate thru DV tool 4 hrs. Circulated 15 sacks. Stage 2: 850 sx PSL "C" (65-30-6%) + 4/10% CF-14 + 5# salt + 5# Gilsonite + 1/4# Celloseal (yield 1.98, wt 12.4). Tailed in w/100 sx Class "H" Neat (yield 1.18, wt 15.6). PD at 12:30 PM 5-1-92. Did not circulate cement - did circulate Gilsonite and Flocele on 2nd stage. WOC 48 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 5-6-92
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE MAY 13 1992

CONDITIONS OF APPROVAL, IF ANY: