

+15F  
DP

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504

RECEIVED  
MAY 13 1992

WELL API NO. 30-015-26978
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Thomas AJJ Com
8. Well No. 5
9. Pool name or Wildcat North Dagger Draw U/Penn

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>19S</u> Range <u>25E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3553' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing, Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
TD 8200'. Reached TD 5-3-92. Ran 199 joints 7" 23# and 26# J-55 and N-80 casing set 8200'. Float shoe set 8200', float collar set 8158'. DV tool set 5605'. Cemented in 2 stages. Stage 1: 700 sx Class "H" + 5#/sx Silicalite + 5#/sx Gilsonite + 1/4# Floseal + 4/10% Halad-14 (yield 1.35, wt 15.1). PD 3:30 AM 5-5-92. Circulate thru DV tool 3 hrs. Circulated 100 sacks to pit. Stage 2: 850 sx Lite + 5# Gilsonite + 1/4# Floseal + 5#/sx Salt (yield 1.92, wt 12.5). Tail in w/100 sx "C" Neat (yield 1.18, wt 15.6). PD 8:08 AM 5-5-92. Circulated 125 sx to pit. Bump plug to 3500 psi, held okay. WOC 18 hrs. Drill out DV tool at 5605'. Perforated 7776-7822' w/ 30 - .50" holes (2 SPF) as follows: 7776, 77, 78, 79, 80, 81, 82 (14 holes), 7794, 96, 97, 98, (8 holes), 7818, 20, 21, and 7822' (8 holes). Acidize perfs 7818-22' w/500g. 20% NEFE. Acidize perfs 7776-98' w/1000g. 20% NEFE. Flush on 1st zone 7818-22 communicated w/perfs 7776-98'. Acidize perfs 7776-7822' w/15000g. 20% NEFE acid + balls.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 5-11-92  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

MAY 25 1992