

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-015-27049
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED JUL 28 1995 OIL CON. DIV. DIST. 2
2. Name of Operator Mewbourne Oil Company	
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	7. Lease Name or Unit Agreement Name Angell Ranch "26" State
4. Well Location Unit Letter <u>A</u> : <u>990</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>26</u> Township <u>19S</u> Range <u>27E</u> NMPM <u>Eddy</u> County	8. Well No. 1
9. Pool name or Wildcat Angell Ranch Atoka (Morrow)	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-11-95 CIBP set @ 10,620'. Tested to 1,000#. Capped with 35' cement.

5-12-95 Perforated Wolfcamp Formation from 8448'-58', 8548'-52', and 8616'-30' with 2 SPF for a total of 59 holes. Acidized with 4500 gal. 15% HCL. Recovered trace of oil. Well is not productive.

Mewbourne Oil proposes to plug and abandon as follows:

1. Set a CIBP @ 8400'. Cap with 35' cement. Circulate hole with mud.
2. Set a 100' cement plug from 7732'-7832'. (DV tool @ 7782')
3. Set a 100' cement plug from 3065'-3165' / 2150'-2250'. Tag cement.
4. Set a 100' cement plug from 265'-365'. Tag cement.
5. Set a 10 sk. plug @ surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Ryan TITLE District Manager DATE July 26, 1995
TYPE OR PRINT NAME Kelly Ryan TELEPHONE NO. (505) 393-5905

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 1 1995

CONDITIONS OF APPROVAL, IF ANY: