

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-015-27049
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Angell Ranch "26" State
8. Well No. 1
9. Pool name or Wildcat Angell Ranch Atoka (Morrow)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Mewbourne Oil Company
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	4. Well Location Unit Letter A : 990 Feet From The North Line and 990 Feet From The East Line Section 26 Township 19S Range 27E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 7/28/95 thru 8/02/95

MIRU plugging equipment. Set CIBP @ 8400' and capped with 35' of cement. Spotted 30 sx. cement plugs @ 7832'; 3165' and 2250'. RIH and tagged cement @ 2100'. Spotted 30 sx. cement plug @ 365' and tagged cement @ 120'. Set a 10 sx. cement surface plug, cut off wellhead and installed P & A marker. RDMO plugging equipment and cleaned location.

RECEIVED

SEP 16 1995

Post ID-2
10-20-95

P+H

OIL CON. DIV.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gregory Milner TITLE Engineer DATE 9/14/95
TYPE OR PRINT NAME Gregory Milner TELEPHONE NO. (505) 393-5905

(This space for State Use)

APPROVED BY Ken Livingston TITLE F.O. 2 DATE 11-22-95
CONDITIONS OF APPROVAL, IF ANY: