

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

UNIT, API NO.

30-015-27172

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

L-2764

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Irish Hills KW State

1. Type of Well:

OIL

WELL ☐

GAS

WELL ☒

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

8. Well No.

3

3. Address of Operator

105 South 4th St., Artesia, NM 88210

9. Pool name or Wildcat

Undesignated

4. Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 2

Township 19S

Range 24E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3703' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Swab test Canyon; perforate, treat Cisco ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-10-93. RUPU. Set RBP @ 7581', tested to 2000#. Set packer @ 7416'. Swabbed perfs 7491-7525' (Canyon perfs). Drop down and straddled Canyon perfs 7633-51'. Set RBP @ 7708', tested to 1200#. Set packer @ 7657'. Swab/tested for 3 days. Moved RBP to 7414', tested to 1800#. TOH w/tubing and packer. Perforated Cisco 6687-6741' (1 SPF) as follows: 6687, 89, 91, 95, 97, 99, 6701, 12, 14, 23, 25, 39 and 6741'. TIH w/packer and tubing. Acidized perfs 6687-6741' w/2000g. 15% NEFE. Flow/swab tested well. Moved RBP to 6646', tested to 2000#. TOH w/tubing and packer. Perforated Cisco (1 SPF-5 holes) 6593, 94, 95, 96 and 6597'. TOH w/casing guns. TIH w/packer and tubing. Set packer 6514'. Acidized perfs 6593-97' w/1000g. 7½% NEFE. Swabbed well 3-19-22-93. TOH w/packer and tubing. Perforated Cisco (1 SPF) as follows: 6487, 88, 89, 6542, 43, 44 and 6545'. TIH w/RBP, packer and tubing. Straddled perfs 6487-89' and acidized w/1000g. 15% NEFE. Drop down and straddled perfs 6542-45' and acidized w/1000g. 15% NEFE. Set packer at 6415'. Swabbed perfs 6487-6545'. TIH w/packer and tubing to RBP at 6646' Unset RBP. Reset RBP at 6811' test to 1500#. Set packer at 6480', test to 700#. RU swab and swab Cisco perfs 6487-6741'. 3-26-93. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor

DATE 4-28-93

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: