			811 S. 1-1 ST		
			ARTE . NM 382	n 0-283 ¢	C
orm 3160-5	UNITED STAT	TES	ARTE FORM APPI		0
une 1990)	DEPARTMENT OF THE		Budget Bureau No		
	BUREAU OF LAND MAN		Expires: March		
			5. Lease Designation		-
			NM-	045276	
SUNDRY NOTICES AND REPORTS ON WELLS		ORTS ON WELLS	6. If Indian, Allottee or Tribe Name		-
o not use this form for prope Use "APPLICATION"	oosals to drill or to deepen or ree N_FOR_PERMIT for such propo	entry to a different reservoir.			
	SUBMIT IN TRIPLIC		7. If Unit or CA, Agree	ment Designation	-
Type of Well					
	NJECTION				
Well Well Oth			8. Well Name and No.		
Name of Operator	/		Pres WEL	on 35N Fed	
CONOCO INC. Address and Telephone No.			9. API Well No.	L#5	
·			30-0	5-27626	
10 DESTA DR. STE 100W, ocation of Well (Footage, Sec., T., R.,	MIDLAND, TX. 79705 (915) 686 -	5424	10. Field and Pool, or	Exploratory Area	
		MAY 2 1 1995	Dagger Draw Up.	Penn So. (Associated)	
SURFACE: Coco TD: Same			11. County or Parish,	State	
Sec	0 FNC 1980 F . 35, TZOS - R	~44£ (2001). D	Eddy	Co.	
CHECK APPROPRIA	TE BOX(s) TO INDICATE NA	TURE OF NOTICE, REPO	RT, OR OTHER DAT	\	
TYPE OF SUBMISS		TYPE OF AC			
Notice of Intent		Abandonment	Change of Plans		
		Recompletion	New Construction		
X Subsequent Report		Plugging Back	Non-Routine Frac		
, , , , , , , , , , , , , , , , ,		Casing Repair	Water Shut-Off	to any	
Final Abandonment	Notice	Altering Casing			
	· · · · · · · · · ·	X Other	Conversion to Inje	CION	
		∧ oner	Dispose Water		
Describe Proposed or Completed Ope directionally drilled, give subsurfac	erations (Clearly state all pertinent details, and ce locations and measured and true vertical de	Change pump give pertinent dates, including estimated o apths for all markers and zones pertinent to	(Note: Report results of multiple Completion or Recompletion Re	port and Log form)	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	erations (Clearly state all pertinent details, and ce locations and measured and true vertical de parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod ng unit. Cleaned up location.	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated o opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	···
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	•••
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping	^c parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod	give pertinent dates, including estimated of opths for all markers and zones pertinent to d latched onto fish.POOH w/ rods	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping	Parted rods. RIH w/ fishing tools and s down tubing. RIH w/ pump and rod is down tubing. RIH w/ pump and rod ing unit. Cleaned up location.	give perlinent dates, including estimated o spths for all markers and zones perlinent to d latched onto fish.POOH w/ rods is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work, this work.)* and pump. Layed down bac ced pump out . Unable to h	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping	Parted rods. RIH w/ fishing tools and s down tubing. RIH w/ pump and rod g unit. Cleaned up location.	give perlinent dates, including estimated of opths for all markers and zones perlinent to d latched onto fish.POOH w/ rods is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work this work.)*	port and Log form.) If well is rods. SION. ang on because	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping	Parted rods. RIH w/ fishing tools and s down tubing. RIH w/ pump and rod g unit. Cleaned up location.	give perlinent dates, including estimated o spths for all markers and zones perlinent to d latched onto fish.POOH w/ rods is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work, this work.)* and pump. Layed down bac ced pump out . Unable to h	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping	Parted rods. RIH w/ fishing tools and s down tubing. RIH w/ pump and rod g unit. Cleaned up location.	give perlinent dates, including estimated o spths for all markers and zones perlinent to d latched onto fish.POOH w/ rods is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work, this work.)* and pump. Layed down bac ced pump out . Unable to h	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping	Parted rods. RIH w/ fishing tools and s down tubing. RIH w/ pump and rod g unit. Cleaned up location.	give perlinent dates, including estimated o spths for all markers and zones perlinent to d latched onto fish.POOH w/ rods is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re late of starting any proposed work, this work.)* and pump. Layed down bac ced pump out . Unable to h	port and Log form.) If well is	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping hereby certify that the bregong is the Signed Mun Automation his space for Federal or State office us roved by inditions of approval, if any:	Parted rods. RIH w/ fishing tools and parted rods. RIH w/ fishing tools and ls down tubing. RIH w/ pump and rod ng unit. Cleaned up location. Ann E. Ritchi Trite	give pertinent dates, including estimated of ppths for all markers and zones pertinent to d latched onto fish.POOH w/ rods . ls. Changed out 26-7/8" rods. Spa is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re faile of Starting any proposed work in this work.)* and pump. Layed down back ced pump out . Unable to he Date	port and Log form.) If well is I rods. SION. ang on because 4-24-96	
3-21-96 MIRU. POOH w/ 3-22-96 Poured chemicals beam off pumping hereby certify that the foregoing is full Signed Mut State office us roved by inditions of approval, if any:	parted rods. RIH w/ fishing tools and parted rods. RIH w/ pump and rod ls down tubing. RIH w/ pump and rod ng unit. Cleaned up location. an E. Ritchi Title Title Title Title	give pertinent dates, including estimated of ppths for all markers and zones pertinent to d latched onto fish.POOH w/ rods . ls. Changed out 26-7/8" rods. Spa is. Changed out 26-7/8" rods. Spa	(Note: Report results of multiple Completion or Recompletion Re faile of Starting any proposed work in this work.)* and pump. Layed down back ced pump out . Unable to he Date	port and Log form.) If well is I rods. SION. ang on because 4-24-96	