

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

FEB 21 1994

WELL API NO.

30-015-27757

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210 (505) 748-1471

7. Lease Name or Unit Agreement Name

Mobil AOB

8. Well No.

1

9. Pool name or Wildcat

North Dagger Draw Upper Penn

4. Well Location

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 1 Township 20S Range 24E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3603' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Production Casing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8264'. Reached TD 2-14-94. Ran 201 joints 7" 26# N-80 and J-55 and 7" 23# J-55 casing set 8264'. Float shoe set 8264', float collar set 8223'. DV tool set 6010'. Cemented in two stages as follows: Stage I - 300 sx "H" + 5#/sx CSE + 5#/sx Gilsonite + 1/4#/sx Celloseal + .65% CF-14 (yield 1.33, wt 15.1). Tailed in w/200 sx "H" + 10% Thixad + 8#/sx Hiseal + 10% Salt (yield 1.38, wt 15.5). PD 5:08 AM 2-16-94. Bumped plug to 1750 psi for 1 minute. Circulated 169 sacks. Circulated thru DV tool 3 hours. Stage II - 800 sx PSL "C" + 5#/sx Salt + 5#/sx Gilsonite + 1/4#/sx Celloseal + .4% CF-14 (yield 2.01, wt 12.4). Tailed in w/100 sx "H" Neat (yield 1.18, wt 15.6). PD 9:45 AM 2-16-94. Bumped plug to 3000 psi for 1 minute, float and casing held OK. Circulated 123 sacks. WOC 18 hours.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Supervisor

DATE 2-18-94

TYPE OR PRINT NAME Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

SUPERVISOR DISTRICT II

APPROVED BY

TITLE

DATE

MAR 3 1994

CONDITIONS OF APPROVAL, IF ANY: