DEPARTME BUREAU OF	TED STATES NT OF THE INTERIOR LAND MANAGEMENT	Drawer DD Artesem ANMO 88210 Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-76936
)o not use this form for proposals to d	AND REPORTS ON WELLS rill or to deepen or reentry to a different reservoir. OR PERMIT—" for such proposals	
SUBMI	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Type of Well XX Well Gas Other	SEP - 7 : 94	8. Well Name and No. Sunflower AHW Federal #3
Name of Operator YATES PETROLEUM CORPORATION Address and Telephone No.	(505) 748-14719 . C. D.	9. API Well No. 30-015-28027
105 South 4th St., Artesia, Location of Well (Footage, Sec., T., R., M., or Survey	NM 88210	10. Field and Pool, or Exploratory Area Wildcat Abo
1980' FNL & 660' FEL of Sect:	ion 31-T19S-R24E (Unit H, SENE)	11. County or Parish, State
CHECK APPROPRIATE BO	(s) TO INDICATE NATURE OF NOTICE, REPO	Eddy Co., NM DRT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO	
Notice of Intent		Change of Plans New Construction
Subsequent Report	Recompletion Plugging Back Casing Repair	Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Cosing X Other Perfs & acid	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well
Describe Proposed or Completed Operations (Clearly stat	e all pertinent details, and give pertinent dates, including estimated date of star	Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true ve 8-11-94 - Set and tested and pulling unit. Installed cass bit, stabilizer, drill coll. swivel and drill out DV too Circulate hole clean. TOOH with bit, scraper and 2-7/8 2-7/8" tubing, scraper and GR/CCL/CBL logs. TOOH. 8-12-94 - TIH w/4" casing g 4122-4128' (7 holes) and 41 TIU w/PBP measker and 2-7/8	<pre>eall pertinent details, and give pertinent dates, including estimated date of star rical depths for all markers and zones pertinent to this work.)* chors. Made cut off on 5-1/2" casing. sing head and BOP. Tested casing to 1 ars and 2-7/8" tubing. Tag DV tool at 1. Test casing to 2200 psi for 7 minu with 2-7/8" tubing, drill collars, st " tubing to 4208'. Displaced hole wit bit. TIH w/logging tools. Pressured uns and perforated 4122-4161' w/22 .42 47-4161' (15 holes). TOOH with casing " tubing. Set RBP at 4180'. Pulled u Acidized perforations 4122-4161' wit."</pre>	Completion or Recompletion Report and Log form.) ting any proposed work. If well is directionally drilled, Moved in and rigged up 000 psi. TIH w/4-3/4" 3155'. Rig up power tes. TIH with bit to 4208'. abilizer and bit. TIH h 2% KCL water. TOOH with casing to 1000 psi. Ran " holes as follows: guns and rig down wireline. p and set packer at 4084'.
give subsurface locations and measured and true ve 8-11-94 - Set and tested and pulling unit. Installed cass bit, stabilizer, drill coll. swivel and drill out DV too Circulate hole clean. TOOH with bit, scraper and 2-7/8 2-7/8" tubing, scraper and GR/CCL/CBL logs. TOOH. 8-12-94 - TIH w/4" casing g 4122-4128' (7 holes) and 41 TIH w/RBP, packer and 2-7/8 Spot acid to end of packer. and ball sealers. Swabbing	<pre>rical depths for all markers and zones permitted to us work.) chors. Made cut off on 5-1/2" casing. sing head and BOP. Tested casing to 1 ars and 2-7/8" tubing. Tag DV tool at 1. Test casing to 2200 psi for 7 minu with 2-7/8" tubing, drill collars, st " tubing to 4208'. Displaced hole wit bit. TIH w/logging tools. Pressured uns and perforated 4122-4161' w/22 .42 47-4161' (15 holes). TOOH with casing " tubing. Set RBP at 4180'. Pulled u Acidized perforations 4122-4161' wit</pre>	Completion or Recompletion Report and Log form.) ting any proposed work. If well is directionally drilled, Moved in and rigged up 000 psi. TIH w/4-3/4" 3155'. Rig up power tes. TIH with bit to 4208'. abilizer and bit. TIH h 2% KCL water. TOOH with casing to 1000 psi. Ran " holes as follows: guns and rig down wireline. p and set packer at 4084'.