Submit 3 Copies to Appropriate District Office

State of New Mexico Energy * Tinerals and Natural Resources Department

LOLLS C.TM
Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

WELL API NO. 30-015-28033

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

5. Indicate Type of Lease FEE X

NOV

4 1994

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFEN OR PLUM BACK TOA DIFFERENT RESERVION. USE "APPLICATION FOR PERMAT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUS FOR PERMIT FORM C-101) FOR SUCH PROPOSALS	DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	OCT 31.94	6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUS FOR PERMIT FORM C-101) FOR SUCH PROPOSALS	OUNDRY MOTIONS AND DEDODT	S ON WELLS	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
Office Section Section	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION"	TO DEEPEN OR PLUG BACK TO A ON FOR PERMIT"	7. Lease Name or Unit Agreement Name
WILL X WELL SOME OPERATION 2. Name of Operator YATES PETROLEUM CORPORATION 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 4. Well Location Unit Latter G: 1980 Feet From The North Line and 1980 Feet From The East Life Section 2.8 Township 195 Range 25E NMFM Eddy County 10. Elevation (Show Norther DF, RKB, RT, GK, GC) 3.483' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMPOT. CASING TEST AND CEMPOT. PLUG AND ABANDONMENT CASING TEST AND CEMPOT. CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TO THER: 12. Describe Proposed or Completed Operations (Clearly rate all pertinent details, and give pertinent dates, including enimated date of starting any proposed worth) SEE RULE 1103. 5. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H". 10#/sack gilsonite. 1/4#/sack celloseal and 22 CaCl2 (yield 1.55, sacks 12% Thixset "H". 10#/sack gilsonite. 1/4#/sack celloseal and 22 CaCl2 (yield 1.55, nours. Ran Temperature Survey and found top of cement at 30", Ran, 1". Tagged cement at 83.0" NOURL Resumed drilling. 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-10 and 90 sacks Pacesetter Lite () 10#/sack gilsonite. 1/4#/sack celloseal and 28.0" Ran, 1". Tagged cement at 83.0" Ran, 1". Tagged cement at 7:00 FM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. 10-21-94. WOC 21 hours and 15 minute	1. Type of Well:		Hinkle ALD
2. Name of Operator 2. Address of Operator 3. Address of Operator 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 3. Address of Operator 105 South Fourth Dagger Draw Upper Penn, Fourth Dagger Draw U	MEIT X MEIT QUIE	R	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210 North Jeager Draw Upper Penn, for North Unit Letter G: 1980 Feet From The North Section 28 Township 195 Range 25E NMFM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3.483' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND GEMENT JOBS THE SPUN, TESUME drilling, surface casing OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed worth SEE RULE 1103. SPUNDED A 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas sacks 12T Thisset "If", 10#/sack gilsonite, 1/4#/sack celloseal and 2% Cacl2 (yield 1.55, sacks 12T Thisset "If"), 10#/sack gilsonite, 1/4#/sack celloseal and 2% Cacl2 (yield 1.55, sacks 12T Thisset "If"), 10#/sack gilsonite, 1/4#/sack celloseal and 2% Cacl2 (yield 1.32, weight 14.8) PB 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 14.8) PB 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement at 801, 4 Ran 1". Tagged cement at 83, 1 Nours. Ran Temperature Survey and found top of cement at 801, 4 Ran 1". Tagged cement at 830 AM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-13 Propose found to 10 sacks 12C Cacl2. PD 7:00 AM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-13 Propose found to 10 sacks 12C Moching and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling.	2. Name of Operator	•••	
4. Well Location Unit Letter G: 1980 Feet From The North Line and 1980 Feet From The East Line Section 28 Township 195 Range 25E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3483 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent dataits, and give pertinent datas, including estimated date of starting any proposed work) SEE RULE 1103. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notiched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.55, sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% Cacle (yield 1.32, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% Cacle (yield 1.32, weight 14.8). Pp 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80'. Mr. 1 Tagged cement at 83'. North 1 Production Clerk Substitute of the production of the part of			9. Pool name or Wildcat
Weil Location Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line Section 28 Township 19S Range 25E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3483' GR GR GR GR GR GR GR GR	 Address of Operator 105 South Fourth Street - Artesia, NM 	88210	North Dagger Draw Upper Penn,
Unit Letter G: 1980 Feet From The North Line and 1980 Feet From The East Interest Color of the Part of the Section 28 Township 198 Range 25E NMFM Eddy County 10. Elevation (Show whether DF, RKB, Rt, GR. etc.) 10. Elevation (Show whether DF, RKB, Rt, GR. etc.) 3483' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK	ATT II Tio-	- .	.
Section 28 Township 198 Range 235 North March 10. Elevation (Show whether Dr. R.B.R. R.G.R. at) 10. Elevation (Show whether Dr. R.B.R. R.G.R. at) 3483' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. CHANGE PLANS OTHER: Spud, resume drilling, surface casing	Unit Letter _G : 1980 Feet From TheN	Iorth Line and 19	980 Feet From The East Line
10. Elevation (Show whether DF, RRB, RT, GR, etc.) 3483' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON GRANDER PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB GOTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. 13. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40° of 20" conductor pipe. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40° of 20" conductor pipe. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40° of 20" conductor pipe. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40° of 20" conductor pipe. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40° of 20" conductor pipe. Spudded a 26" hole at 9:30 AM 10-19-94. Treas 10. 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack cellosseal and 2% Cacl2 (yield 1.55, asception 1.55,	Service 28 Township 195	Range 25E	NMPM Eddy
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING THER: Spud, resume drilling, surface casing OTHER: Thou of the at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.95, sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 3% weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to	Section 20 10. Elevation	(Show whether DF, RKB, RT, GR, etc.)	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including entimated date of staning any proposed work) SEE RULE 1103. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% Cac12 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 8.0". Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% Cac12. PD 7:00 AM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. I hereby certly that the information above of processor of the best of my knowledge and belief.		3483' GR	V////////////////////////////////
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including entimated date of staning any proposed work) SEE RULE 1103. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% Cac12 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 8.0". Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% Cac12. PD 7:00 AM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. I hereby certly that the information above of processor of the best of my knowledge and belief.	Check Appropriate Box to	Indicate Nature of Notice,	Report, or Other Data
PERFORM REMEDIAL WORK CHANGE PLANS CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Spud, resume drilling, surface casing OTHER: Spud, resume dri		ļ SL	JBSEQUENT REPORT OF:
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING CASING TEST AND CEMENT JOB OTHER: Spud, resume drilling, surface casing OTHER: Spud, resume drilling, surface casing OTHER: Spud, resume drilling, surface casing of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed wort) SEE RULE 1103. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% Cacil2 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite c, 10#/sack gilsonite, 1/4#/sack celloseal and 3% veight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80', Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% Cacil2. PD 7:00 AM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. Thereby certify that the information above if price and complete to the best of my knowledge and belief. SIONATURE Rusty Klein TIME Production Clerk PATE 10-26-94 505-748-1471 THE Production Clerk TIME Production Clerk TIME Production Clerk		DON REMEDIAL WORK	ALTERING CASING
OTHER: OTHER: Spud, resume drilling, surface casing OTHER: Spud, setting and spud surface and setting and set		COMMENCE DRILL	ING OPNS. DUG AND ABANDONMENT
OTHER: Spud, resume drilling, surface casing 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, OK. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80 m, Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% CaCl2. PD 7:00 AM 10-21-94. WOC. Drilled out at 7:00 PM - 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. The Production Clerk DATE DATE OF THE PROPERTY NAME. The Production Clerk DATE DATE OF THE PROPERTY NAME. The Production Clerk DATE DATE OF THE PROPERTY NAME. THE Production Clerk DATE DATE OF THE PROPERTY NAME.	TENNI OF MILE, ME WINDOW		CEMENT JOB
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.55, sweight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80', Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% CaCl2. PD 7:00 AM 10-21-94. WoC. Drilled out at 7:00 PM - 10-21-94. WoC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. The Production Clerk DATE 10-26-94 Type or FURNIT NAME Rusty Klein TILE PROVENCE.	PULL OR ALTER CASING L	OTUER Spud, I	resume drilling, surface casing
Spudded a 26" hole at 9:30 AM 10-15-94 with rat hole machine. Set 40' of 20" conductor pipe. Cemented to surface. Resumed drilling a 14-3/4" hole with rotary tools at 8:00 AM 10-19-94. TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80', Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% CaCl2. PD 7:00 AM 10-21-94. WOC. Drilled out at 7:00 PM - 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief. Thereby certly that the information above is frue and complete to the best of my knowledge and belief.	OTHER:		
TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80'. Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% CaCl2. PD 7:00 AM 10-21-94. WOC. Drilled out at 7:00 PM	12. Describe Proposed or Completed Operations (Clearly state all perwark) SEE RULE 1103.	tinent details, and give pertinent dates, it	conductor pipe.
TD 1156'. Ran 26 joints of 9-5/8" 36# J-55 (1294.07') of casing set at 1156'. 1-Texas Pattern notched guide shoe set at 1156'. Insert float set at 1127.49'. Cemented with 200 sacks 12% Thixset "H", 10#/sack gilsonite, 1/4#/sack celloseal and 2% CaCl2 (yield 1.55, weight 14.6) and 900 sacks Pacesetter Lite C, 10#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.99, weight 12.4). Tailed in with 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 9:45 PM 10-20-94. Bumped plug to 500 psi, 0K. Cement did not circulate. WOC 4 hours. Ran Temperature Survey and found top of cement at 80'. Ran 1". Tagged cement at 83'. Spotted 100 sacks Class C 2% CaCl2. PD 7:00 AM 10-21-94.7 WOC. Drilled out at 7:00 PM 10-21-94. WOC 21 hours and 15 minutes. Cut off and welded on flow nipple. Reduced hole to 8-3/4". Resumed drilling. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. Thereby cerufy that the information above is true and complete to the best of my knowledge and belief. The complete to the best of my knowledge and belief. The complete to the best of my knowledge and belief. The complete to the complete to the best of my knowledge and belief. The complete to the complete to the best of my knowledge and belief.	Cemented to surface. Resumed drilling	a 14-5/4 Hore water	•
TYPE OR PRINT NAME RUSTY Klein THE Production Clerk 505-748-1471 TELEPHONE NO.	Pattern notched guide shoe set at 1130 sacks 12% Thixset "H", 10#/sack gilson; weight 14.6) and 900 sacks Pacesetter 1 CaCl2 (yield 1.99, weight 12.4). Tailed 14.8). PD 9:45 PM 10-20-94. Bumped polyhours. Ran Temperature Survey and four Spotted 100 sacks Class C 2% CaCl2. Place 10-21-94. WOC 21 hours and 15 minutes	ite, 1/4#/sack cellosea Lite C, 10#/sack gilson ed in with 200 sacks "C lug to 500 psi, 0K. Ce	1 and 2% CaCl2 (yield 1.55, ite, 1/4#/sack celloseal and 3% " 2% CaCl2 (yield 1.32, weight ment did not circulate. WOC 4 Ran 1". Tagged cement at 83'.
TYPE OR PRINT NAME RUSTY Klein THE Production Clerk 505-748-1471 TELEPHONE NO.		· · · · · ·	
TYPE OR PRINT NAME RUSTY Klein Type OR PRINT NAME RUSTY Klein Type OR Size Use)	I hereby certify that the information above is true and complete to the best of	my knowledge and belief.	10-26-94
TYPE OR PRINT NAME RUSTY Klein TELEPHONE NO. 1771	SIGNATURE TUSTOF PULL	me Productio	
CD - constant State Liter	, ,		TELEPHONE NO.
	(This space for State Use)		NOV

SUPERVISOR, DISTRICT II

APPROVED BY -

a reporter mility