

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-28053
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-6096
7. Lease Name or Unit Agreement Name State K
8. Well No. 3
9. Pool name or Wildcat N. Dagger Draw Upper Penn

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED SEP 23 '94 O. C. D. ARTESIA, OFFICE
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	
4. Well Location Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line Section 28 Township 19S Range 25E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3480' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate & acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-20-94 - Cleaned location, set and tested anchors and markers. Made cut off on 7" casing. Moved in and rigged up pulling unit. Nippled up tubinghead and installed BOP. TIH with bit, stabilizer, drill collars and 2-7/8" tubing to DV tool at 5989'. Rigged up power swivel and drilled out DV tool. Tested casing to 2000 psi, OK. TOOH with 2-7/8" tubing, drill collars, stabilizer and bit. TIH w/bit, scraper and 2-7/8" tubing to 8170'. Displaced casing with 2% KCL. TOOH with tubing, scraper and bit. Rigged up wireline and TIH with logging tools. Pressured casing to 1000 psi and ran CBL/CCL/GR log. TOOH with logging tool. Shut down.

9-21-94 - Rigged up wireline. TIH w/4" casing guns and perforated 7785-7804' w/12 .42" holes (2 SPF) as follows: 7785, 87, 98, 7800, 02 & 7804'. TOOH with 4" casing guns and rigged down wireline. TIH w/packer and 2-7/8" tubing. Spotted 2 bbls 20% NEFE acid across perforations 7785-7804'. Moved up and set packer at 7762'. Acidized perforations 7785-7804' with 1000 gallons 20% NEFE acid with scale and paraffin inhibitor. Rigged up swab. Swabbing.

9-22-94 - Swabbing.

9-23-94 - Unset packer at 7762'. TOOH with tubing & packer. Released to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 9-23-94  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)  
**ORIGINAL SIGNED BY TIM W. GUM**  
**DISTRICT II SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 2 1995