Submit 3 Copies to Appropriate District Office	State of New Mex Energy, Minerals and Natural Res	ources Department	Form C-103 C151 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 7 30-015-28148
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 8	Jai 13 '95	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		C. S. E.	6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PRO	ICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PER -101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: OL GAS WELL X WELL	OTHER		Patriot AIZ
2 Name of Operator			8. Well No. 5
YATES PETROLEUM CORPO	RATION		9. Pool name or Wildcat
3. Address of Operator 105 South Fourth Stre	et - Artesia, NM 88210		N. Dagger Draw Upper Penn
A Well Location		Line and) Feet From The Line
Unit Letter		25E	NMPM Eddy County
Section 21	Township 19S Ra		
3482' GR			
NOTICE OF INTENTION TO:			
	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	
CASING TEST AND			
OTHER:		OTHER: Perfora	
 Differ: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. 1-9-95 - Cleaned location, set and tested anchors and markers. 1-10-95 - Moved in and rigged up pulling unit. Nippled up BOP. TIH with bit, stabilizer, drill collars and 2-7/8" tubing to DV tool at 6693'. Rigged up power swivel and drilled out DV tool. Tested casing to 1500 psi for 10 minutes, OK. TOOH with 2-7/8" tubing, drill collars, stabilizer and bit. TIH with bit, scraper and 2-7/8" tubing to 8239'. Circulated casing with 2% KCL water. TOOH with 2-7/8" tubing, scraper and bit. Rigged up wireline. TIH with logging tools and ran GR/CCL/CBL log. TOOH with logging tools. Shut down. 1-11-95 - TIH w/4" casing gun and perforated 7679-7786' w/34 .50" holes (2 SPF) as follows: 7679, 81, 83, 93, 95, 97, 7701, 05, 22, 24, 26, 28, 30, 32, 82, 84 & 7786'. TOOH with 4" casing guns and rigged down wireline. TIH w/RBP, packer and 2-7/8" tubing. Set RBP - at 7827'. Tested RBP to 1000 psi, OK. Set packer at 7765'. Acidized perforations 7782-7786' w/5000 gallons 20% NEFE acid with scale and paraffin inhibitor and ball sealers. Unset packer at 7765'. Dropped down and unset RBP at 7827'. Moved up and reset RBP at 7827'. Tested RBP to 1000#, OK. Set packer at 7609'. Acidized perforations 7679-7732'. Tof5'. Tested RBP to 1000#, OK. Set packer at 7609'. Acidized perforations 7679-7732'. Iherdy cetty that the information above is true and complete to the best of my taowledge and behet. SIONATURE August Klein 			
(This space for State Use)			FEB 1 1995
SUPERV	ISOR. DISTRICT II	тп.е	DATE

-

WROLTD BY.