Submit 3 Copies to Appropriate District Office State of New Mexico Energy Minerals and Natural Resources Department	Form C-103 Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240 RECEIVED RECEIVED Santa Fe, NM 87505	WELL API NO. 30-015-28457
P.O. Drawer DD, Artesia Charles ARTESIA Santa Fe, NM 87505	sIndicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM \$7419 (L 91 St 7)	∘State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7Lease Name or Unit Agreement Name Millman State
Type of Well: OIL GAS WELL OTHER TA	
₂Name of Operator SDX Resources, Inc.	¾Vell No. 1
Address of Operator PO Box 5061, Midland, TX 79704	Pool name or Wildcat Wildcat Group 3
Well Location Unit Letter M 660 Feet From The South Line and 660	Feet From The West Line
Section 11 Township 19S Range 28E	NMPM Eddy County
₁₀Elevation (Show whether DF, RKB, RT, GR, etc.	
11 Check Appropriate Box to Indicate Nature of Notice, Rep	•
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
DI LIC AND ABANDON	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	PNS. PLUG AND ANBANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME	PNS. PLUG AND ANBANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEMES OTHER: OTHER: Temporarily A	PNS. PLUG AND ANBANDONMENT Abandon Abandon
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME	PNS. PLUG AND ANBANDONMENT Abandon Abandon
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEMES OTHER: OTHER: Temporarily A Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including es	PNS. PLUG AND ANBANDONMENT Abandon Abandon
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily A 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including es work) SEE RULE 1103.	PNS. PLUG AND ANBANDONIMENT ENT JOB Abandon Stimated date of starting any proposed
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily A 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including es work) SEE RULE 1103. 4/12/02 - MIRU. Set CIBP @6250'. 4/13/02 - Roll csg w/150 bbls pkr fl. Test CIBP & csg to 500# for 30 min. Witnessed by Phil H	PNS. PLUG AND ANBANDONIMENT ENT JOB Abandon Stimated date of starting any proposed
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily A **Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including es work) SEE RULE 1103. 4/12/02 - MIRU. Set CIBP @6250'. 4/13/02 - Roll csg w/150 bbls pkr fl. Test CIBP & csg to 500# for 30 min. Witnessed by Phil H on CIBP.	PNS. PLUG AND ANBANDONIMENT ENT JOB Abandon Stimated date of starting any proposed
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily Assorbed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 4/12/02 - MIRU. Set CIBP @6250'. 4/13/02 - Roll csg w/150 bbls pkr fl. Test CIBP & csg to 500# for 30 min. Witnessed by Phil H on CIBP. Well TA 4/13/02	PNS. PLUG AND ANBANDONIMENT ENT JOB Abandon Stimated date of starting any proposed
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily Assorbed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including eswork) SEE RULE 1103. 4/12/02 - MIRU. Set CIBP @6250'. 4/13/02 - Roll csg w/150 bbls pkr fl. Test CIBP & csg to 500# for 30 min. Witnessed by Phil H on CIBP. Well TA 4/13/02	PNS. PLUG AND ANBANDONMENT ENT JOB Abandon Stimated date of starting any proposed awkins w/NMOCD. Spot & displace 25 sx plug
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily Avord See Rule 1103. 4/12/02 - MIRU. Set CIBP @6250'. 4/13/02 - Roll csg w/150 bbls pkr fl. Test CIBP & csg to 500# for 30 min. Witnessed by Phil H on CIBP. Well TA 4/13/02	PNS. PLUG AND ANBANDONMENT ENT JOB Abandon Ab
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily Associated and pertinent details, and give pertinent dates, including estated in the control of the	PNS. PLUG AND ANBANDONMENT ENT JOB Abandon Ab
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily / **Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including es work) SEE RULE 1103. 4/12/02 - MIRU. Set CIBP @6250'. 4/13/02 - Roll csg w/150 bbls pkr fl. Test CIBP & csg to 500# for 30 min. Witnessed by Phil H on CIBP. Well TA 4/13/02 Temporary until Complete to the best of my knowledge and belief. SIGNATURE Describe Proposed or Commented Operations (Clearly state all pertinent details, and give pertinent dates, including es work) SEE RULE 1103. Title Regulatory Tech	PNS. PLUG AND ANBANDONMENT ENT JOB Abandon Abandon Abandon Abandon Abandoned Status approved Abandoned Status approved
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: OTHER: Temporarily Associated and pertinent details, and give pertinent dates, including estated in the control of the	PNS. PLUG AND ANBANDONMENT ENT JOB Abandon Abandon Abandon Abandoned Status approved

CONDITIONS OF APPROVAL, IF ANY:





