Submit 3 Copies to Appropriate District Office

State of New Mexico Ainerals and Natural Resources Department Ener,

Form	C-103
Revise	d 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

30	 -	0	1	5	_	2	8	5	5	2
		_	_	_	_			_	_	_

DISTRICT II Santa Fe, New Mexico 87504-2088		JO 013 20332				
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	8/304-2088	5. Indicate Type of Lease STATE X FEE			
DISTRICT III		6. State Oil & Gas Lease No.				
1000 Rio Brazos Rd., Aztec, NM 87410		LG-864				
SUNDRY NOTICES	AND REPORTS ON WELL	LS				
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN (OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR	. USE *APPLICATION FOR PER FOR SUCH PROPOSALS)	IMIT TO THE PARTY OF THE				
1. Type of Well:						
OAL X WELL	OTHER		Amole AMM State Com			
2. Name of Operator		4 10 66	8. Well No.			
YATES PETROLEUM CORPORATIO			3			
3. Address of Operator 105 South 4th St., Artesia	- m 00010 OIL		9. Pool name or Wildcat			
105 South 4th St., Artes1a	1, NM 0021U	नामला उ	Dagger Draw Upper Penn, North			
4. WELLIAGARION	,	[일왕기, 경 • • • 1980	Feet From The West Line			
Unit Letter N: 660 I	est From The Bouth	Line and	rea from the time			
Section 16	Township 19S Rar	nge 25E i	NMPM Eddy County			
	10. Elevation (Show whether I		\(\lambda \) \(\la			
	3500'	GR	V/////////////////////////////////////			
11. Check Appr	ropriate Box to Indicate N	Nature of Notice, Re	eport, or Other Data			
NOTICE OF INTEN	TION TO:	SUB	SEQUENT REPORT OF:			
	<u> </u>	REMEDIAL WORK	ALTERING CASING			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	HEMEDIAL WORK				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT .			
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB			
OTHER:		OTHER: Perforate	e and acidize X			
		<u> </u>				
12. Describe Proposed or Completed Operations (work) SEE RULE 1103.						
1 13-15-96 - Cleaned loc	ation, set and test	ed anchors. Mo	ved in and rigged up pulling			
unit Installed tubinghead and BOP. Tested casing to 1900 psi. Tim with bit, stabilizer,						
drill collars and 2-7/8" tubing. Drilled out DV tool at 6223'. Tested casing to 2200						
psi. TOOH. TIH with bit, scraper and 2-7/8" tubing to 8306'. Displaced casing with 2% KCL water. TOOH. TIH with logging tools and ran CBL/CCL/GR log. TOOH with logging						
	H with logging tool	s and ran CBL/C	CL/GR log. Took with logging			
tools Shut down						
1-16-96 - Rigged up wireline. TIH with 4" casing guns and perforated $7704-7790$ ' w/18						
.42" holes as follows: 7704, 06, 24, 26, 28, 30, 32, 34, 36, 38, 60, 62, 68, 70, 76,						
78, 88 & 7790' (1 SPF - Canyon). TOOH with casing guns and rigged down wireline. TIH						
with RBP, packer and 2-7/8" tubing. Set RBP at 7834'. Started break down on perforations 7760-7790' - broke down - communicated with upper perforations. Pulled up and set packer						
at 7645'. Acidized perforations 7704-7790' with 3000 gallons 20% NEFE acid and ball						
at /645'. Acidized peri	orations //04-//90	m thru perforat	ions to knock balls off. Reset			
sealers. TIH and releas	ed perforations 770	4-7790' with 20	0000 gallons gelled 20% NEFE			
Thereby certify that the information above, is took and o	complete to the best of my knowledge and	belief.	CONTINUED ON NEXT PAGE:			
Kunt Ala)	Production C	Clerk 1-16-96			
SIGNATURE / COLOR	<u> </u>	TUE				
TYPEOR PRINT NAME Rusty Klein			<u>тецерноме но. 505/748-1</u> 471			
(This space for State Lise)						

APPROVED BY -

ORIGINAL SIGNED BY TIM W. GUM

DISTRICT II SUPERVISOR

... TITLE -

JAN 2 3 1996