

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-28558
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South Fourth Street - Artesia, NM 88210

4. Well Location
Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 15 Township 19S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3456' GR

7. Lease Name or Unit Agreement Name
Boyd BN

8. Well No.
2

9. Pool name or Wildcat
Dagger Draw Upper Penn, North

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONTINUED FROM PREVIOUS PAGE:

at 7801'. Shut down.

12-8-95 - Set packer at 7757'. Break down perforations 7780-7784' - perms communicated with upper perforations. Unset packer. Pulled up and set packer at 7663'. Acidized perforations 7726-7784' with 2000 gallons 20% NEFE acid and ball sealers. Released packer and ran down thru perforations to knock balls off. Pulled up and reset packer at 7663'. Acidized perforations 7726-7784' with 10000 gallons 20% NEFE gelled acid and ball sealers. Swabbed. Unset packer. Dropped down and unset RBP. TOOH with tubing, packer and RBP. Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Rusty Klein*

TITLE Production Clerk

DATE 12-8-95

505-748-1471
TELEPHONE NO.

TYPE OR PRINT NAME Rusty Klein

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

DEC 1 9 1995

APPROVED BY

TITLE

DATE