Submit 3 Copies to Appropriate District Office

State of New Mexico inergy, Minerals and Natural Resources Department

Form	C-10	3 (
Revise	d 1-1	1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO.

DISTRICT II P.O. Drawer DD, Anesia, NM 88210 Santa Fe, New Mexico 87504-2088		30-013-23-2 3-33		
		5. Indicate Type of Lease STATE FEE	\mathbf{x}	
DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease No.	<u> </u>
			 	,,,,,,
	ES AND REPORTS ON W		<i>\ </i>	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name		
1. Type of Well:	TON SOUR PHOPOSALS.)		-	
Off X WELL X WELL	OTNER		Patrick API	
2. Name of Operator			8. Well No.	
YATES PETROLEUM CORPORA	TION	•	1	
3. Address of Operator			9. Pool name or Wildcat	
105 South Fourth Street	- Artesia, NM 8821)	Dagger Draw Upper Penn, Nor	th
4. Well Location				
Unit Letter D: 660	_ Feet From The North	Line and 660	Feet From The West	Line
Section 10	Township 19S	Range 25E	NMPM Eddy Co	unty
		er DF, RKB, RT, GR, etc.)	<i>וווווווווווווווווווווווווווווווווווו</i>	
<i>\////////////////////////////////////</i>	////X	5' GR	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	
11. Check A	ppropriate Box to Indicat	e Nature of Notice, F	leport, or Other Data	
NOTICE OF INTE	NTION TO:	SUE	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON] REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONM	ENT [
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
Producti		on Call Call MED	X	
OTHER:		J OTHEN: 110ddct1	44	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sterring and proposed work) SEE RULE 1103.				
TD 8250'. Reached TD at 4:30 PM 10-15-95. Ran 202 joints of 7" 26# & 23# casing as				
C 11 15 dedute of	7" 26# N-80 candblac	rad (605 72'): 4	inimate lof 17 11 26# J-95 sand-	
blasted (166.79'); 1 7" 26# N-80 sandblasted marker joint (20.55'); 59 joints of 7" 26# J-55 varnished (2423.83'); 92 joints of 7" 23# J-55 varnished (3778.22'); 30 joints of				
J-55 varnished (2423.83'); 92 joints of 7" 23# J-55 varnished (3778.22); 30° joints of				
7" $26\#$ J-55 varnished (1235.88') and 1 /" $26\#$ N-80 sandblasted marker joint (17.75)				
(Total 8250.94') of casing set at 8250'. Float shoe set at 8250'. Float collar set at				
8208'. DV tool set at 6016'. Marker joint set at 7477'. Cemented in two stages as				
follows: Stage 1: 500 sacks Super 11, 8#/sack gilsonite, 5#/sack salt, 4/10% Halad 9				
and 1/4#/sack flocele (yield 1.55, weight 13.5). PD 5:22 AM 10-17-95. Circulated 97 sacks cement. Circulated through DV tool for 3-1/2 hours. Stage 2: 800 sacks Halli-				
burton Lite Premium Plus, 5#/sack salt, 4/10% Halad 9 and 1/4#/sack flocele (yield 2.09,				
weight 12.4). Tailed in with 100 sacks Class H (yield 1.18, weight 15.6). PD 10:51 AM				
10-17-95. Bumped plug to 3300 psi for 1 minute. Circulated 91 sacks. WOC. Released				
rig at 3:00 PM 10-17-95. NOTE: Circulating sub set at 8167'. Waiting on completion				
unit.		<u> </u>		
I hereby cerufy that the information above is true	and complete to the best of my knowledge	and belief.		
SIGNATURE TUSTED	en	mme Production	Clerk DATE 10-25-95	
SIGNATURE RUSTY Klein			505-748-1471 Telephone no.	

(This space for State HANDIMAL SIGNED BY TIM W. GUM

OCT **3 0 19**95.

DATE -