

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-28631
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Patrick API
8. Well No.	2
9. Pool name or Wildcat	Dagger Draw Upper Penn, North

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>9</u> Township <u>19S</u> Range <u>25E</u> NMPM <u>Eddy</u> County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3519' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-29-95 - Moved in and rigged up pulling unit. Nippled up 11" 3000 X 7-1/16" 3000 tubinghead. TIH with bit, stabilizer, drill collars and tubing to 6010'. Drilled out DV tool at 6028'. Tested to 1500#. TIH and tagged PBTD at 8179'. Circulated hole with 2% KCL water.

12-30-95 - TOOH with bit, stabilizer, drill collars and tubing. TIH with bit and scraper through DV tool. TOOH with bit and scraper. Rigged up wireline. TIH with logging tools and ran CBL log. Shut down and shut in for holiday.

12-31-1-2-96 - Shut down for holiday.

1-3-96 - TIH with tubing to 7837'. Spotted 250 gallons 20% NEFE acid. TOOH with tubing. Rigged up wireline. TIH with 4" Select Fire guns and perforated 7784-7823' w/18" 40" holes as follows: 7784, 86, 88, 90, 92, 94, 96, 97, 7806, 08, 10, 12, 14, 16, 18, 20, 22 & 7823'. TOOH with guns and rigged down wireline. TIH with 7" Uni-V packer and set at 7707'. Acidized perforations 7784-7823' with 2000 gallons 20% NEFE acid & ball sealers. Surged balls off and reacidized with 20000 gallons gelled acid & ball sealers. Swabbing.

1-4-96 - Swabbed. Loaded tubing & unset packer. TOOH. Released to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 1-9-96
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 18 1996