

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P. O. Box 1980, Hobbs, NM 88240

DISTRICT II

811 S. 1st Street, Artesia, NM 88210-2834

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088

Santa Fe, New Mexico 87504-2088

COPY FEB - 5 1997

WELL API NO. 30-015-28746
5. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
6. State Oil & Gas Lease No. 001789
7. Lease Name or Unit Agreement Name Merchant State
8. Well No 2
9. Pool Name or Wildcat East Millman (QU-GB-SA), East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Bass Enterprises Production Company	
3. Address of Operator P. O. Box 2760 Midland, Texas 79702-2760	
4. Well Location Unit Letter <u>L</u> : <u>1980'</u> Feet From The <u>South</u> Line and <u>660'</u> Feet From The <u>West</u> Line Section <u>1</u> Township <u>19S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3402.1 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <u>Plugback</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP @ 7670' and dump bail 35' cement on top.
- 2) RIH to 5050' and spot plug, pump 35 sx Class C cement to spot cement from 5067' to 4884', tag TOC @ 4921', pump 80 sx Class C cement and tag TOC @ 3039'.
- 3) RIH with 4" casing gun loaded with 1 JSPF @ 120 degree phasing with 23 gram Owen charges and perf the following interval:
2597-2601' (4', 4 holes)
2692-2704' (12', 12 holes)
- 4) Acidized perfs with 1512 gals 15% HCl acid with additives and dropped 27 1.3 SG ball sealers.
- 5) Frac'd with 28,417 gals YF 130 and 110,500 lbs 20/40 Brady Sand with proppet.
- 6) Clean out sand and re-tag PBTD @ 3001'.
- 7) Return well to production.

Certified 9960 132 455

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tami L. Wilber TITLE: Production Clerk DATE: 2/3/97

TYPE OR PRINT NAME Tami L. Wilber Telephone No. (915) 683-2277

(This space for State Use)

APPROVED BY: DISTRICT II SUPERVISOR TITLE: _____ DATE: FEB 7 1997

CONDITIONS OF APPROVAL, IF ANY: