

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-102  
Revised February 10, 1994  
Instruction on back  
Submit to Appropriate District Office  
State Lease - 4 Copies  
Fee Lease - 3 Copies

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

APR 11 1997

AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

API Number <b>30-015-29166</b>	Well Code <b>96686</b>	Well Name <b>Shugart Wellcamp West</b> <del>N. Shugart Morrow</del>
Property Code <b>19509</b>	Property Name <b>West Shugart 30 Federal</b>	Well Number <b>1</b>
OGRID No. <b>147380</b>	Operator Name <b>Penwell Energy Inc.</b>	Elevation <b>3606'</b>

Surface Location

UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
F	30	18 S	31 E		1980	North	1980	West	Eddy

Bottom Hole Location If Different From Surface

UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County

Dedicated Acres <b>320</b>	Joint or Infill	Consolidation Code	Order No.
-------------------------------	-----------------	--------------------	-----------

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED  
OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	<p>OPERATOR CERTIFICATION</p> <p>I hereby certify the the information contained herein is true and complete to the best of my knowledge and belief.</p> <p><i>Brenda Coffman</i> Signature</p> <p>Brenda Coffman Printed Name</p> <p>Production Analyst Title</p> <p>August 5, 1996 Date</p> <p>SURVEYOR CERTIFICATION</p> <p>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision and that the same is true and correct to the best of my belief.</p> <p>May 13, 1996 Date Surveyed</p> <p><i>W.D. No. 61936</i> Signature &amp; Seal of Professional Surveyor</p> <p>W.D. No. 61936 Certificate No. Gary L. Jones 7977</p> <p>BASIN SURVEYS</p>
--	---