						· .		X.		
	1	NEW M	EXICO OIL CO	ONSERVATION	I COMMISSI	ON				
	ISTRIBUTION		Santa I	Fc, New Mexico	•					
NTA FE									┽╌┼╼╸	
ND OFFICE	- 2					┝━┥		┼╌┼╌┼╸	4 	
ANPORTER			WEL	L RECORI)			<u> </u>		
ORATION OFF										
Sub 1	mine								· ·	
Mail de	District O	ffice, Oil Cons	ervation Commissi	on, to which Forn	a C-101 was sen	t not		+		
later th	an twenty d	ays after comp	letion of well. Follo	ow instructions in	Rules and Regul	ations		┼╌╬╾┼╼	┽╾┼╾╴╢	
of the (INTUPLICATE	II State Lan	a submit o Cop	•		LEA 640 ACRE	_!] s	
	Jack	L. McClel		1 6 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Mark St	ate	LOCATE	WELL CORR	БСЧТІ.Т .	
:ll No	1			of Sec1	.8 T			28 - E	NMPM	
			North							
			State Land the Oil							
lling Con	menced	February	27,	, 19.65 Drillin	ng was Completed	Marc	h 22		19	
	-		ortez Drilli							
lre ss		Box 58	4, Artesia,	New Mexico			********	*****		
vation ab	ove sea level	at Top of Tubi	ng Head	513 GL	The in	formation give	n is to b	e kept confi	dential until	
			, 19			1	$R \in C$	SEIV	FR	
									لويه بعده	
	100			DIL SANDS OR Z			٨٥	D 1 6 10		
1, from.	1906) /=-/#=	to <u>1915</u>	No. 4	, from	*****		<u>R I 7 19</u>	53	
2, from	1969) 	1988	No. 5	, from	******	to[), 6, , , , , , ,	*****	
			to							
			to				••••••••••••••••••••••••••••••••••••••		****	
			to				•••••••	********		
. 3, from			to		******	feet	•••••••••••••	•••••••••••••••••••••••••••••••••••••••	••••••	
4, from	•••••••		to			feet		*****		
				CASING RECO	RD					
SIZE	WEIG PER F		OR SD AMOUNT	KIND OF SHOE	CUT AND PULLED FROM	BEREARA	FOR A WIONE		PUBDOSA	
					T CLEED THOA		PERFORATIONS		PURPOSE	
<u>-5/8</u> -1/2	<u>24 1</u> 1591			Float Float				Wate		
-1/2		. <u>/ </u>	W 2032				<u></u>	011	String	
			MUDDIN	G AND CEMENT	ING RECORD		·	<u> </u>		
HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	G	MUD RAVITY	AMOUNT OF MUD USED		D D	
12"	8 - 5/8	392	50 sx	pump						
8"	5-1/2	2032	<u>110 sx</u>	pump			- <u>-</u>			
			<u></u>	<u> </u>				<u>. </u>	.	
			1	1		·	1		· •	
			RECORD OF	PRODUCTION A	ND STIMULAT	TION				
		(Record	the Process used, I	No. of Ots. or Gal	s. used. interval	treated or show	L)			
erfora	ted 1 sh		ot 1968, 196					, 1983, :	1984 , 19	
			***************************************	••••••••••••••••••••••••••••••••••••••	*****	********			••••••	
			idized with							
bs, sa	nd. Pe	rforated	l shot per f	oot 1906 - 1	5', 1918, 1	920, 1922	, 192	3 , 19 24 8	and 1925	
			Fraced with							
			ell-flowing			·····				
ult of Pro	duction Stin	ulationW	ell_flowing	75 BOPD						

• •

,

.

......Depth Cleaned Out......

المراجعة

......