NO. OF COPIES RECEIVED	#				Form C-103 Supersedes Old
SANTA FE	1	NEW A	MEXICO OIL CONSI	ERVATION COMMISSION	<i>C-102 and C-103</i> Effective 1-1-65
FILE	1-				5a. Indicate Type of Lease
U.S.G.S.					State XX Fee.
OPERATOR	2				5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					
OIL GAS WELL OTHER-					7. Unit Agreement Name
2. Name of Operator JACK L. MCCLELLAN					8. Farm or Lease Name
3. Address of Operator					9. Well No.
P. O. Box 343, Roswell, New Mexico					10. Field and Pool, or Wildcat
UNIT LETTER G . 2310 FEET FROM THE NORTH LINE AND 1650 FEET FROM					
THE EAST LINE, SECTION 13 TOWNSHIP 19-3 RANGE 23-L NMPM.					MPM.
15. Elevation (Show whether DF, RT, GR, etc.)					12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK		Pį	LUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
BULL OR ALTER CASING		CH	HANGE PLANS	CASING TEST AND CEMENT JOB	
OTHER					
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1708. PURSUANT TO YOUR VERBAL INSTRUCTIONS, THIS WELL WILL BE FLUGGED AND ABANDONED AS FOLLOWS:					
25 SACK CEMENT PLUG AT TOTAL DEPTH.					
25 SACK PLUG IN AND OUT OF THE SURFACE CASING.					
	5 SACI	C PLUG AT	THE SURFA	CE.	
LOCATION WIL	L BE C	LEANED AN	ID A MARKER	SET.	
					O. C. E. Artelia, day ter
18. I hereby certify that the	information a	bove is true and	complete to the best	of my knowledge and belief.	エティンティロのA May () 配配
SIGNED Jan 1	M:CQ		TITLE		DATE 12/21/67
			· · · · · · · · · · · · · · · · · · ·		
CONDITIONS OF APPROVAL, IF ANY: Spat a 25 sack plug at State of 5/2" Issue +					
conditions of Approval, IF ANY: Spot a 25 sack plug at stub of 5/2" Casing + Luterale between plugs must be filled with much					