-	•		
Form 3160-5 June 1990)	UNI DEPARTMEN BUREAU OF I	ED STATES T OF THE INTERIOR AND MANAGEMENTECEIVI	ED 5 Lease Designation and Serial No. NM 0/5075
Do not i	use this form for proposals to dri	AND REPORTS ON WELLS, D Il or to deepen or reentry to a difference of reentry to a difference of the second	tent reservoir.
1	SUBMIT	IN TRIPLICATE ROSWELL OF	MGMT. 7. If Unit or CA, Agreement Designation 1007 1
1. Type of W			8. Well Name and No.
			
2. Name of (Operator S PETROLEUM CORPORATION	(505) 748-1471	
	and Telephone No.	E MALTAN H	30-015-29358
105	South 4th St., Artesia, 1	NM 88210	10. Field and Pool, or Exploratory Area
4. Location	of Well (Footage, Sec., T., R., M., or Survey D	escription) on 27-T2OS-R24E (Unit H, S	ENE) Cemetary Morrow (gas) 11. County or Parish, State
			Eddy Co., NM
12.	CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF N	OTICE, REPORT, OR OTHER DATA
	TYPE OF SUBMISSION	т	YPE OF ACTION
	Notice of Intent ACCEPTED FC		Change of Plans
	AUGEPTEDIC	Recompletion	New Construction
	X Subsequent Report	1007 Plugging Back	Non-Routine Fracturing
	SEP 0	1997 Casing Repair	Water Shut-Off
	Final Abandonment Netice	Altering Casing Altering Casing Other Perforate	
	Density of the second s	I partiment details and give pertinent dates, including	estimated date of starting any proposed work. If well is directionally drilled, work)*
8-24 Inst coll Drop 957(tool down 8-2 8-2 hole with and hole TIH 8-2 tre	4-97 - Cleaned location, talled tubinghead and BOF lars and 2-7/8" tubing. pped down and tagged PBT O'. Displaced casing wit ls and ran CBL/CCL/GR log n. 5-26-97 - Shut down. 7-97 - Rigged up wireling es as follows: 9384-9388 h casing guns and rigged nippled up tree. Set pa e. Nippled down tree and and flanged up well. So 8-97 - Rigged up swab. G e. Nippled up BOP. TOO ing. TIH with tubing.	 Tested casing to 1900 p Drilled out DV tool at 700 at 9570'. TOOH. TIH with at 2% KCL.water. TOOH, Rig. TOOH with logging tools TOOH with logging tools (20 holes) and 9372-9376 down wireline. TIH with p acker. Swabbed tubing down inippled up BOP. TOOH. F wabbed tubing. Could not get past 4000'. H 50 stands. Found sandling Set packer at 9302'. Nippled 	loved in and rigged up pulling unit.
pac	ker to 1000 psi. Swabbe	d. Shut well in. CONTINUI	ED ON NEXT PAGE:
-		Title Title	Date Date
Signed			
(This a	space for Foderal of State office use) wed by	Title	Date

٠

*See Instruction on Reverse Side

•