				· /)			
	=			, ci			
Submit 3 Copies To Appropriate District	State of	New M	avico	-151	•		
Office				AN	Form C		
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals	and man	Iral Resources	WELL API NO.	Revised March 25	<u>, 1999</u>	
District II				30-015-29628			
811 South First, Artesia, NM 88210	OIL CONSERV	-		5. Indicate Tyr.			
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco Santa Fe, NM 87505			STATE	Lease FEE		
District IV					JAS Lease No.		
2040 South Pacheco, Santa Fe, NM 87505				0. State Off & C	Jas Lease INO.		
SUNDRY NOTIO	CES AND REPORTS OF	N WELLS	,	7. Lease Name	or Unit Agreement		
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEI	PEN OR PLI	JG BACK TO A	Name:			
DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ATION FOR PERMIT" (FORM	M C-101) FC	DR SUCH				
1. Type of Well:				Parkway West Un	nit #28		
Oil Well 🔲 Gas Well 👂	• Other						
2. Name of Operator				8. Well No.			
Ocean Energy, Inc.				2			
3. Address of Operator				9. Pool name or Wildcat			
1001 Fannin, Suite 1600, Houston, Texas 77002			Parkway West Morrow				
4. Well Location			· · · · · · · · · · · · · · · · · · ·		· · ·		
Unit Letter <u>E</u> : <u>1980</u> f	feet from the <u>North</u>	line and	d <u>1310</u> fee	et from the <u>Wes</u>	t line		
Section 28	Township	19S	Range 29E	NMPN	1 Eddy Co	ounty	
	10. Elevation (Show w					Juny	
	GR 3315'		, , , , , , , , , , , , , , , , , , , ,				
11. Check Ar	ppropriate Box to Inc	dicate Na	ature of Notice. F	Report or Other	Data		
NOTICE OF INT	ENTION TO:			SEQUENT REI			
	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASIN		
					ALI LINING CASIN		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND	<u> </u>	
		—			ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D 🗆			
OTHER: CHANGE PERFS IN	SAME ZONE		OTHER:			O	

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Set CIBP @ 11,170' and dump 20' of cement on top of CIBP. Perforate Morrow from 10,880'-886' and test. Clean up well, obtain state potential and put well on line.



I hereby certify that the	information above is true and comp	plete to the b	est of my knowledge and belief.			
signature Aca	nie McMillan	TITLE	Regulatory Specialist	DATE	10/23/00	
Type or print name	Jeanie McMillan		Telephone No. (713) 265-68	834; fax (713) 26	5-8889	
(This space for State use APPPROVED BY	ORIGINAL SIGNED BY TIM W DISTRICT H SUPERVISOR	GUAP			NOV 1	5 2000
Conditions of approval,	if any:	VIILE_	······································	DATE_		

Parkway West Unit 28-2 1980' FNL & 1310' FWL Sec. 28, T-19-S, R-29-E Eddy Co., NM

June 7, 2000 Recomplete in Upper Morrow

Current Production: 71 Mcfpd (5/00 avg.)

1.

- 1) MIRU workover rig. ND tree and NU 5M BOP's.
 - a) Kill well w/2% KCl if necessary.
 - b) Have tree inspected/stump tested.
- 2) Release pkr @ 11,107' and POOH w/2-7/8" tbg.
 - a) Visually inspect tbg. Look for scale, paraffin or rust that might cause problems with the TCP guns.
- RU WL. RIH w/5-1/2",17-20# CIBP. Set CIBP @ <u>+11,15</u>0'. Dump bail 20' of cmt on top of CIBP. POOH and RD WL.
 a) See attached bid from Schlumberger.
- 4) TiH w/2-7/8" tbg open ended to ±10,900'. Circulate 250 bbls of treated pkr fluid in the hole. Spot 100 gals of 10% acetic acid from 10,900' to 10,800'. POOH.
 - a) Pickle tubing if it looks like there is enough scale/rust to cause a problem with the TCP guns.
- 5) PU TCP gun assy w/ mechanical firing head, spacer joint/subs, mechanical gun release, glass disc sub, 5-1/2" 17#-20# pkr,10k Baker FL-22 on/off tool w/2.312" "F" profile, 2 jts tbg, 3-4' pup jt on 2-7/8", 6.5# EUE tbg. RIH w/pkr at ± 10,800', or approximate setting depth to have top shot at 10,880'.
 - a) Put a 200 water cushion above glass disc to slow down bar.
 - b) Make sure to dope pins, not collars, while TIH.
 - c) Rattle tbg if necessary to avoid buildup of debris on glass disc.
 - d) Glass disc is rated at 5000 psi differential, but use a 4000 psi differential maximum.
 - e) See attached TCP diagram.
- 6) RU WL. RIH w/CCL/gamma ray and correlate guns on depth. POOH and RD WL.
 - a) Depth Reference: Schlumberger Platform Express CNL Run #1 dated 7/18/97.
- 7) Space out for 10-12k lbs compression and set pkr with top shot of TCP guns at 10,880'. Test annulus to 2000 psi. Land tbg.
- 8) ND BOP's and NU tree.
- 9) Open well on a 10/64" choke. Drop firing bar and perforate Morrow from 10,880-86". Allow well to clean up to tanks.
- 10) Obtain State potential test and PWOL.

Ronna Pitzer Change C103 - Reperf in same

Fawkway West Unit 28-2 1980' FNL & 1310' FWL Sec. 28, T-19-S, R-29-E Eddy Co., NM Elevation: 3315' GL, 3333' KB

Spud Date: 6/10/97 Completion Date: 9/23/97

Completion

8/97; Perf Morrow:11390-401'; 11,416-26'. FTP 1050psi. Flowing strong gas. Est. rate: 1575 mcfpd. Treated w/2400 gals HCL-methanol-CO2. Flowing w/1300 psi FTP@est rate 4.4 MMcfpd. Turn to production.

2/98: Perf Morrow: 11,198-204', 11,207-21', 11236-45', 11,248-56.' Saw pressure and blow at surface. Surface pressure was 1925 psi by the time gun got to surface. PWOL. FTP 3100 psi, 1.5 MMcfpd.

DST #1 Wolfcamp: Opened tool w/weak blow, increased TOT. Rec'd 180' fluid (50% oil), 2820' wfr (filtrate). IF 500; FF 446; ISI 5340 psi; FS I 5310 psi. 30-60-60-120.

DST #2 Strawn (10,238-65'): Opened tool w/strong blow increasing TOT. GTS 2 min into IS!. IF 190-160; FF 160-266; ISI 3437 psi; FSI 3611 psi. Rec'd 90' condensate and 150' GCM.



PB10 that

				· · · · ·		
Submit 3 Copies To Appropriate District Office <u>District I</u> 1625 N. Franch Dr., Hobbs, NM 88240 <u>District II</u> 811 South First, Artesia, NM 88210 <u>District III</u> 1000 Rio Erazos Rd., Aztec, NM 87410 District IV		and Natu VATION outh Paci	Iral Resources I DIVISION heco	WELL API NO. 30-015-29628 5. Indicate Ty STATE	Form C-103 Revised March 25, 1999	
2040 South Pacheco, Santa Fe, NM 87505	Santa Fe, NM 87505			6. State Oil & C	ias Lease No.	
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC. PROPOSA_S.)	CES AND REPORTS O ALS TO DRILL OR TO DEED ATION FOR PERMIT" (FOR	PEN OR PLU	JG BACK TO A	7. Lease Name Name:	or Unit Agreement	
1. Type of Well: Oil Well Gas Well	Other			Parkway West Un	it #28	
2. Name of Operator				8. Well No.		
Ocean Energy, Inc. 3. Address of Operator 1001 Fannin, Suite 1600, Houston, Texas 77002				2 9. Pool name or Wildcat Parkway West Morrow		
4. Well Location Unit Letter <u>E</u> : 1980	feet from the <u>North</u>	line and	d <u>1310</u> fee	et from the <u>Wes</u>	tline	
Section 28	Township		Range 29E		f Eddy County	
	10. Elevation (Show w GR 3315'	hether Di	R, RKB, RT, GR, etc.			
11. Check Ap NOTICE OF INT	ppropriate Box to Ind	dicate Na		Report or Other I SEQUENT REI		
	PLUG AND ABANDON		REMEDIAL WORK			
	CHANGE PLANS		COMMENCE DRIL	LING OPNS. 🗌		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D 🗌	ABANDONMENT	
OTHER: CHANGE PERFS IN	SAME ZONE	X	OTHER:		n	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Set CIBP @ 11,170' and dump 20' of cement on top of CIBP. Perforate Morrow from 10,880'-886' and test. Clean up well, obtain state potential and put well on line.



I hereby certify that the	information above is true and comple	te to the t	est of my knowledge	and belief.		
()	nie McMillan	_TITLE_	Regulatory Special	listDATE_	10/23/00	
Type or p int name	Jeanie McMillan			(713) 265-6834; fax (713)	265-8889	
(This space for State us	ORIGINAL SIGNED BY TIM W. DISTRICT II SUPERVISOR 60	GUM			-	2000
APPPROVED BY	DISTRICT II SUPERVISUIS	TITLE		DAT	NOV 01	E E
Conditions of approval						