

WELL TEST INTERPRET. ON REPORT #:1078532		PAGE: 12, 13-NOV-97
CLIENT : OXY USA INC	DISTRIBUTION OF REPORTS	
REGION :CSD		FIELD:BURTON FLATS
DISTRICT:HOBBS		ZONE :
BASE :MIDLAND		WELL :PEARL ST #1
ENGINEER:C.TAYLOR		LOCATION:S32T19SR29E

SCHLUMBERGER has sent copies of this report to the following:

=====

OXY USA INC
P O BOX 50250
MIDLAND, TX 79710
(3 copies)

Any interpretations or recommendations are opinions and necessarily based on inferences and empirical factors and assumptions, which are not infallible. Accordingly, Schlumberger (Flopetrol Johnston) cannot and does not warrant the accuracy of correctness of any interpretation or measurement. Under no circumstances should any interpretation or measurement be relied upon as the sole basis for any drilling, completion, well treatment or production decision or any procedure involving risk to the safety of any drilling venture, drilling rig or its crew or any other individual. The Customer has full responsibility for all drilling, completion, well treatment, and production procedure, and all other activities relating to the drilling or production operation.