

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-015-29993
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name S. P. Johnson
Well No. 2
Pool name or Wildcat Dagger Draw, Upper Penn, North

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Nearburg Producing Company	
Address of Operator 3300 North A Street, Building 2, Suite 120, Midland, Texas 79705	
Well Location Unit Letter <u>G</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>5</u> Township <u>20S</u> Range <u>25E</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3,499' GR</u>	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Workover</u> <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1). MIRU workover unit.
- 2). Set CIBP @ 7,600' to plug Cisco/Canyon. New PBTD is 7,565'.
- 3). Perforate Wolfcamp as follows: 7,278' - 94' and 7,268' - 78' w/4 JSPF.
- 4). Stimulate as required.
- 5). Produce well.
- 6). RDMO workover unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. Scott Kimbrough TITLE Manager of Drilling and Production DATE 6/24/80

TYPE OR PRINT NAME E. Scott Kimbrough

TELEPHONE NO. (915) 686-8235

(This space for State Use)

APPROVED BY Jim W. Brown TITLE District Supervisor DATE 7-17-98

CONDITIONS OF APPROVAL, IF ANY: