		N.M. Oil G	ion CISP
Form 316 (June 199	DEPARTMEN	TED STATES 811 S. 1st Street NT OF THE INTERIOR Artesia, NM 38210-283	FORM APPROV ED Budget Bureau No. 1004-0135 Expires: March 31, 1993
			5. Lease Designation and Serial No. NM98173
Do not	use this form for proposals to dri	AND REPORTS ON WELLS Il or to deepen or reentry to a different reservoi OR PERMIT-'' for such proposals	6. If Indian, Allottee or Tribe Name r.
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
1. Type o			8. Well Name and No.
	Well Well Other		MILLMAN SE FEDERAL #1
	CHO RESOURCES INC.	OCD ECENT	9. API Well No.
3. Addres	ss and Telephone No.	9701 (915) 683-7443 E ARTES	30015-30376 10. Field and Pool, or Exploratory Area
110 W LOUISIANA STE 410; MIDLAND TX 79701 (915) 683-7443     SIA       4. Location of Well (Footage, Sec., T., R., M., or Survey Description)     SIA			PARKWAY MORROW WEST
4. Locali 2310'	FNL & 660' FWL, SEC. 33, T-19S, R-29	E 222110168	11. County or Parish, State
			EDDY CO., NM
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
			New Construction
	X Subsequent Report	Plugging Back Casing Repair	Won-Routine Fracturing
	Final Abandonment Notice		Conversion to Injection
		Other Add additional Morrow Pay	
	ribe Proposed or Completed Operations (Clearly s	tate all pertinet details and give pertinent dates, including estimated dat	Dispose Water (Note: Report results of multiple completion on Weat     Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is
direc 3-17- CIBP 3-19- P110 3-20- 3-22- bbl. I 3-23- 3-24- 4-1-9 5-3-9 5-4-9 5-6-9	tionally drilled, give subsurface locations and meas 99 MIRU. Kill well w/ 50 bbls FW. ND W @ 11400' cap w/ 35' of cmt in two runs. 99 RU and perf @ 11314-318', 11321-32 sub, pkr, on/off tool, and 355 jts 2-3/8" tb 99 POH w/ tbg & prk. PU & RIH w/ pkr a & 3-22-99 RU and acidize Morrow w/ 100 RD PU. SWI for BU. 99 SITP @ 3450#. Open well on 12/64 of 99 to 4-1-99 Testing well. 9 SWI. 9 MIRU. Frac well w/ 20/40 Bauxite: 29 9 MAde 53 BW. 9 FTP 900 psi, 1500 MCF, 1.5 BC, 1.5 B 9 to 5-11-99 Testing well.	tate all pertinet details, and give pertinent dates, including estimated dat sured and true vertical depths for all markders and zones pertinent to thi /H & NU BOP. Release pkr. POH w/ tbg, subts, on/off too RD WL. SI. 26', 11328-333', 11342-345'. RD. RIH w/ re-entry guide, 2 g to 11,255'. Tested tbg to 10,000 psi. Unable to set pkr. ind set @ 11270'. ND BOP, NU tree. Rig up swab. 00 gals 7-1/2% NEFE, 30% Methanol w/ 300 SCF N2/bbl. ck. 260#, TLTR 251 bbls. Begin recovering load.	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) te of starting any proposed work. If well is s work.)* ol, pkr, & TCP tools. LD. RIH & set -3/8" X 1.81" R Nipple, 10 - 2-3/8"

## RECEIVED

## JUL 26 '99

i

ſ

BLM ROSWELL, NM