

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-30402
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-9688
7. Lease Name or Unit Agreement Name	
Triangle Ranch ASW State Com	
8. Well No.	1
9. Pool name or Wildcat	Red Tank Draw Atoka Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3857' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER
2. Name of Operator	YATES PETROLEUM CORPORATION		
3. Address of Operator	105 South 4th St., Artesia, NM 88210		
4. Well Location	Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line		
Section	<u>13</u>	Township	<u>19S</u>
Range	<u>23E</u>	NMPM	<u>Eddy</u>
County	<u>Eddy</u>		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: Return well to Atoka-Morrow <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Recompletion attempt to Cisco was unsuccessful. Propose to return well to Atoka-Morrow as follows:

1. Load tubing and casing with 2% KCL water. Nipple down tree and nipple up BOP.
2. POOH with tubing, packer and RBP. NOTE: Packer set at 6187' and RBP at 6435'.
3. GIH with overshot for on/off tool. Circulate top of packer packer.
4. Latch onto packer at 7910'. Nipple down BOP and nipple up tree.
5. Swab well down to pull equalizing probe from blanking plug in 1.81" profile in packer on/off tool at 7910'.
6. Swab/flow well.
7. Return well to production from perforations 7976-8094' (Atoka) and 8325-8330' (Morrow).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Dec. 20, 1999

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT H SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 12-23-99

CONDITIONS OF APPROVAL, IF ANY: