| ¹ Submit 3 Copies to Appropriate District Office | State of New M Energy, Minerals and Natural R | | clsr | Form C-103 Revised 1-1-89 |
|--|---|---|---|--|
| <u>DISTRICT I</u> P.O. Bax 1980, Habbs, NM 8824 0 | OIL CONSERVATIO | | WELL API NO. | |
| DISTRICT II | P.O. Box 20 Santa Fe, New Mexico | | 30-015-304 | 02 |
| P.O. Drawer DD, Artesia, NM \$8210 | •••• | 0070 | 5. Indicate Type of Lease STAT | BX FEE |
| DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 | 324 | 2526212820.27 | 6. State Oil & Gas Losse No. LG-9688 | |
| (DO NOT USE THIS FORM FOR PRO DIFFERENT RESER (FORM C | CES AND REPORTS ON WE DPOSALS TO DRILL OR TO DEEPEN AVOIR. USE "APPLICATION BOR DE -101) FOR SUCH PROPOSALS.) | NOR PLUG BACK TOTA | 7. Lease Name or Unit Agreen | nent Name |
| 1. Type of Well: OL CAS WELL X WELL | 181 | THIESIA OF | Tutonala Davah | |
| 2. Name of Operator V | OTHER E | SI DI EL ZI L'OLOLOL | Triangle Ranch A | ASW State Com |
| YATES PETROLEUM CORPOR | ATION | 5/ 51 51 211.00 | . 1 | |
| 3. Address of Operator 105 South 4th St., Art | | | 9. Pool same or Wildcat Red Tank Draw Atc | ka Mannau |
| 4. Well Location | | | <u>L Reu Tank Draw Acc</u> | oka-Morrow |
| Unit Letter :23 | 10 Feet From The South | Line and1980 | 0 Feet From The | est Line |
| Section 13 | Township 195 R | ange 23E | NMPM Eddy | County |
| | | 57' GR | | |
| 11. Check | Appropriate Box to Indicate | | eport, or Other Data | |
| NOTICE OF INT | | | SEQUENT REPORT | OF: |
| | | REMEDIAL WORK | ALTERING | |
| | | COMMENCE DRILLING | | |
| PULL OR ALTER CASING | | CASING TEST AND CE | | |
| Other: | | | | |
| | | OTHER: Return w | <u>ell to Atoka-Morro</u> | w |
| 12. Describe Proposed or Completed Operat | ions (Clearly state all pertinent details, a | 1 | | |
| 12. Describe Proposed or Completed Operative work) SEE RULE 1103. 1-26-2000 - Moved in a Nippled down tree and TIH with retrieving to 1-27-2000 - Finished T Tested packer to 500 p pulled blanking plug. for cleanup. Shut wel Returned well to produ and 8325-8330' (Morrow | nd rigged up pulling u nippled up BOP. TIH a ol and 60 stands tubin IH and latched onto pa si. Swabbed tubing do TOOH and rigged down 1 in. Released well t ction on January 28, 2 | nit. Loaded tub nd give persiment dates, includ nd latched onto g. Shut down fo cker. Nippled d wn to 6000'. Ri slickline. Open o production dep | ing and casing with RBP. Released RBP r night. own BOP. Nippled gged up slickline. ed well up and flow artment. | proposed n 2% KCL. and TOOH. up tree. TIH and wed well |
| work) SEE RULE 1103. 1-26-2000 - Moved in a Nippled down tree and TIH with retrieving to 1-27-2000 - Finished T Tested packer to 500 p pulled blanking plug. for cleanup. Shut wel Returned well to produ and 8325-8330' (Morrow | nd rigged up pulling u nippled up BOP. TIH a ol and 60 stands tubin IH and latched onto pa si. Swabbed tubing do TOOH and rigged down 1 in. Released well t ction on January 28, 2). | nit. Loaded tub nd give periment dates, includ nit. Loaded tub nd latched onto g. Shut down fo cker. Nippled d wn to 6000'. Ri slickline. Open o production dep 000, from perfor | ing estimated date of starting any ing and casing with RBP. Released RBP r night. own BOP. Nippled gged up slickline. ed well up and flow artment. ations 7976-8094' chnician DATE F | proposed n 2% KCL. and TOOH. up tree. TIH and wed well (Atoka) eb. 28, 2000 |
| work) SEE RULE 1103. 1-26-2000 - Moved in a Nippled down tree and TIH with retrieving to 1-27-2000 - Finished T Tested packer to 500 p pulled blanking plug. for cleanup. Shut wel Returned well to produ and 8325-8330' (Morrow | nd rigged up pulling u nippled up BOP. TIH a ol and 60 stands tubin IH and latched onto pa si. Swabbed tubing do TOOH and rigged down 1 in. Released well t ction on January 28, 2). | nd give periment dates, include nit. Loaded tub nd latched onto g. Shut down fo cker. Nippled d wn to 6000'. Ri slickline. Open o production dep 000, from perfor | ing and casing with RBP. Released RBP r night. own BOP. Nippled a gged up slickline. ed well up and flow artment. ations 7976-8094' chnician DATE F | proposed n 2% KCL. and TOOH. up tree. TIH and wed well (Atoka) eb. 28, 2000 |
| work) SEE RULE 1103. 1-26-2000 - Moved in a Nippled down tree and TIH with retrieving to 1-27-2000 - Finished T Tested packer to 500 p pulled blanking plug. for cleanup. Shut wel Returned well to produ and 8325-8330' (Morrow I hereby certify that the isformation above is the SKONATURE TYPE OR FRIPT NAME | nd rigged up pulling u nippled up BOP. TIH a ol and 60 stands tubin IH and latched onto pa si. Swabbed tubing do TOOH and rigged down 1 in. Released well t ction on January 28, 2). | nd give periment dates, includ nit. Loaded tub nd latched onto g. Shut down fo cker. Nippled d wn to 6000'. Ri slickline. Open o production dep 000, from perfor | ing and casing with RBP. Released RBP r night. own BOP. Nippled a gged up slickline. ed well up and flow artment. ations 7976-8094' chnician DATE F | proposed n 2% KCL. and TOOH. up tree. TIH and wed well (Atoka) |