

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

157
Form C-103
Revised March 25, 1999

WELL API NO.
30-015-30881

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Yates Petroleum Corporation

3. Address of Operator
105 S. 4th Street Artesia, NM 88210

4. Well Location

Unit Letter **A** : **660** feet from the **North** line and **660** feet from the **East** line

Section **29** Township **19S** Range **25E** NMPM **Eddy** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3511' GR

7. Lease Name or Unit Agreement Name:

Binger AKU

7. Well No.
#4-H

8. Pool name or Wildcat
Dagger Draw Upper Penn, N.

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Acidize <input checked="" type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/9/00 - Move in and rig up pulling unit.

10/17/00 - TIH with coil tubing to 9102'. Acidize open hole 8800-9102' with 7500 gals 20% gelled IC HCL.

Move coil tubing and acidize open hole 8500-8800' with 7500 gals 20% IC HCL.

Move coil tubing and acidize open hole 8200-8500' with 7500 gals 20% IC HCL.

Move coil tubing and acidize open hole 7900-8200' with 7500 gals 20% IC HCL.

10/24/00 - TIH and retrieve whipstock.

10/25/00 - Tag CIBP at 7700'. Mill out and push to 8000'.

10/27/00 - Turn well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Susan Herpin* TITLE Engineering Technician DATE January 31, 2002
Type or print name Susan Herpin Telephone No. 505-748-1471

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

FEB 12 2002

APPROVED BY *BT* TITLE _____ DATE _____

Conditions of approval, if any:

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED
DATE 08-10-2001 BY 60322 UCBAW