Submit 3 Copies To Appropriate District Office <u>DISTRICT 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>DISTRICT II</u> 811 South First, Artesia NM 88210 <u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 2040 S. Pacheco, Santa Fe, NM 87505	State of Ne Energy, Minerals an OIL CONSERVA 2040 Sout Santa Fe, N	d Natural Resources TION DIVISION h Pacheco	WELL API NO. 30-015-31049 5. Indicate Type of Lease STATE \boxtimes FEE \blacksquare 6. State Oil & Gas Lease No. 25596				
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPO	7. Lease Name or Unit Agreement Name:						
DIFFERENT RESERVOIR. USE "APPLICAT 1. Type of Well:	TION FOR PERMIT" (FORM \mathbf{S} 10	RECEIVED	Idaho-Red Hackle 15				
2. Name of Operator David H. Arrington Oil & Gas, Inc.	A752	OCD ARIESIN ST	8. Well No.				
3. Address of Operator P.O. Box 2071 Midland, Texas 79702			9. Pool name or Wildcat Undesignated Hoag Tank (Morrow)				
4. Well Location Unit letter <u>B</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line							
Section 15	Township 19S	Range 36E	NMPM County Eddy				
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL: 3958', RKB 3977'							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTEN	TION TO:	SUBSEQUENT REPORT OF:					
	LUG AND ABANDON 📗	REMEDIAL WORK	🔟 ALTERING CASING 🕅				
TEMPORARILY ABANDON 🔲 CI	HANGE PLANS	COMMENCE DRILLING O	PNS. X PLUG AND ABANDONMENT 🗐				
	IULTIPLE OMPLETION	CASING TEST AND CEME					
OTHER:	<u>ه</u> .	OTHER: Complete Dr	illing 🛛				

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Spud at 4:00 a.m. on May 3, 2000. Drill 17 1/2" hole to 400'. Lost circulation at 70'. Dry drill remainder. Ran and cement 13 3/8" casing at 400'. Cemented with 440 sx. Run temperature survey. Top of cement at 110'. Run 1" pipe to 90'. Pump 150 sx cement with no returns. Pump Ready Mix at surface. Drill 12 1/4" hole to 1870'. Loss of circulation at 975'. Dry drill remainder. Ran and cement 8 5/8" casing. Cement with 750 sx cement with no returns. Run temperature survey. Top of cement at 570'. Run 1"pipe, tag at 529'. Cemented with 225 sx cement. Circulate 20 sx. Drill 7 7/8" hole 7485'. 8 5/8" casing parted at 92'. Fish bad casing down to 169'. Replaced 8 5/8" casing. Continued drilling with down hole motor to 8300'. Run open hole logs. Ran and cement 5 1/2" casing at 8288' with 500 sx of cement. DV Tool at 4931'. Cement DV Tool with 750 sx cement. Ran CBL. Top of cement at 2840'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE	TITLE	President	DAT	E <u>July 10, 2000</u>		
Type or print name David H. Arrington			Telephone No. 915/682-6685			
(This space for State use) APPROVED BY	🖌 TITLE	District Sym	ison	DAGT 25 200		
Conditions of approval, if any:						