Submit 3 Copies

to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department



Form C-103 Revised 1-1-89

AUG 2 6 2001

_____DATE _

District Office		•	1
DISTRICT I	OIL CONSERVATION	ON DIVISION	
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pacheco St.		WELL API NO.
DISTRICT II	Santa Fe, NM 87505		30-015-31726
P.O. Drawer DD, Artesia, NM 88210	,		5. Indicate Type of Lease
DISTRICT III			STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
CHINDRY NOTICES AND DEPORTS ON WELLS		648	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			
		7. Lease Name or Unit Agreement Name	
(FORM C	-101) FOR SUCH PROPOSALS.)		OXY RUGER STATE
1. Type of Well:			
OIL GAS WELL X	OTHER		
2. Name of Operator	OTILK		8. Well No.
· •	.		o. Wen no.
OXY USA WIP Limited Partners 3. Address of Operator	mp ,	192463	0. Pool some or Wildow
P.O. Box 50250 Midland, TX	70710 0050		9. Pool name or Wildcat
4. Well Location	79710-0250		UNDSG MILLIMAN MORROW, SOUTH
Unit Letter M: 660	Feet From The SOUTH	r:	0 Feet From The WEST Line
Onit Letter	reet from the	Line and	Feet From TheLine
Section 9	Township 19S R	Range 28E	NMPM EDDY County
		ner DF, RKB, RT, GR, etc.)	
		3546′	
11. Check An	propriate Box to Indicate	Nature of Notice	Papart or Other Date
		1	
NOTICE OF INT	ENTION TO:	SOB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	BLUC AND ABANDON [DEMEDIAL WORK	П и т гания в наше
PENFONIVI NEIVIEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	L ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. X PLUG AND ABANDONMENT
PULL OR ALTER CASING	,	CASING TEST AND CE	MENT 100 X
TOLE ON ALTER CASING		CASING TEST AND CE	MENI JOB [4]
OTHER:		OTHER:	
 Describe Proposed or Completed Operations work) SEE RULE 1103. 	ations (Clearly state all pertinent det	ails, and give pertinent date	s, including estimated date of starting any proposed
WOIR) SEE ROLE 1103.			
			A Marina State
			A A
			7
			ાં કે જેવાન
	SEE OTHER SIDE		Door
			MECEIVED
			TOU ARTESIA
			±*. □
			t_{max}
I hereby certify that the information above is true	and complete to the best of my knowledge ar	nd belief.	
1.6		_	. ا - ا م
SIGNATURE	тт	LE <u>Sr. Regulatory A</u>	nalyst DATE B(17(0)
TYPE OR PRINT NAME David Stewart			TO PRIORE NO
David Stewart			TELEPHONE NO. 915-685-5717
(This space for State Use)	IGINAL SIGNED BY TIM W.	GUM	
1211	STRICT II SUPERVISOR	- 	
	PINIOL II BULERTIOUR		a a 200

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY_

ATTACHMENT C-103
OXY USA WTP LP
OXY RUGER STATE #1
SEC 9 T19S R28E
EDDY COUNTY, NM

NOTIFIED NMOCD 6/22/01 OF SPUD. MIRU UTI 508, SPUD WELL @ 2400hrs MDT 6/23/01. DRILL 17-1/2" HOLE TO TD @ 435', 6/24/01, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 435'. M&P 151sx 65:35 C/POZ W/ 6% BENTONITE + 2% $CaCl_2 + .25\#/sx$ CELLOFLAKES + 5#/sx LCM FOLLOWED BY 200sx CL C W/ 2% $CaCl_2$, DISP W/ FW, PLUG DOWN 6/24/01, CIRC 27sx CMT TO PIT, POOH, WOC-4hr. NMOCD NOTIFIED, DID NOT WITNESS. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 1000#/s, OK. NU BOP & TEST BOP & CASING TO 500#/s, OK. TOTAL WOC-18hrs, RIH & TAG, DRILL OUT & DRILL AHEAD 6/25/01.

DRILL 12-1/4" HOLE TO TD @ 3028', 6/29/01, CHC. RIH W/ 9-5/8" 36# K55 CSG & SET @ 3028'. M&P 850sx 35:65 POZ/C W/ 6% BENTONITE + 2% CaCl₂ + .25#/sx CELLOFLAKES + 5#/sx LCM FOLLOWED BY 200sx Cl C CMT W/ 1% CaCl₂, DISP W/ FW, PLUG DOWN 6/30/01. CIRC 150sx CMT TO SURFACE, WOC-4hrs, NOTIFIED NMOCD DID NOT WITNESS. CUT OFF CSG & INSTALL B SEC, TEST TO 1500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES AND CSG TO 2500#, OK. RIH, DO CMT & SHOE, DRILL NEW FORMATION, TEST CSG, OK. DRILL AHEAD 7/1/01.

DRILL 8-3/4" HOLE TO 11220' 7/31/01, CIRC & CONDITON HOLE. RIH W/ OH LOGS, POOH, CIRC HOLE, WO ORDERS. TURN OVER RIG & WELLBORE TO MARBOB ENERGY 8/2/01.