- 1. All Company and Contract personnel admitted on location must be trained by a qualified H_2S safety instructor to the following:
 - A. Characteristics of H₂S
 - B. Physical effects and hazzards
 - C. Proper use of safety equipment and life support systems. D. Principle and operation of H_2S detectors, warning system
 - and briefing areas.
 - E. Evacuation procedure, routes and first aid.
 - F. Proper use of 30 minute pressure demand air pack.
- 2. H_2S Detection and Alarm Systems
 - H2S detectors and audio alarm system to be located at bell nipple, A. end of blocie line (mud pit) and on derrick floor or doghouse.
- 3. Windsock and/or wind streamers
 - A. Windsock at mudpit area should be high enough to be visible.
 - B. Windsock at briefing area should be high enough to be visible.
 - с. There should be a windsock at entrance to location.
- 4. Condition Flags and Signs
 - A. Warning sign on access road to location.
 - B. Flags to be displayed on sign at entrance to location. Green flag, normal safe condition. Yellow flag indicates potential pressure and danger. Red flag, danger, H2S present in dangerous concentration. Only emergency personnel admitted to location.
- 5. Well control equipment
 - A. See exhibit "E"
- 6. Communication
 - A. While working under masks chalkboards will be used for communication.
 - 3. Hand signals will be used where chalk board is inappropriate.
 - C. Two way radio will be used to communicate off location in case of emergency help is required. In most cases cellular telephoned will be available at most drilling foreman's trailer or living quarters.
- 7. Drillstem Testing
 - A. Exhausts will be watered.
 - B. Flare line will be equipped with an electric ignitor or a propane pilot light in case gas reaches the surface.
 - C. If the location is near to a dwelling a closed DST will be performed.