





STRAWBERRY "7" FED. #2
 Located at 1300' FNL and 1750' FEL
 Section 7, Township 19 South, Range 31 East,
 N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786
 1120 N. West County Rd.
 Hobbs, New Mexico 88241
 (505) 393-7316 - Office
 (505) 392-3074 - Fax
 basinsurveys.com

W.O. Number: 2416AA - KJG CD#4

Survey Date: 04-08-2002

Scale: 1" = 2 MILES

Date: 04-09-2002

DEVON
SFS OPERATING,
INC.