

G.L. 383,
N.R. 3840RALPH LOUIS NO. 1 DEEPAN 21 IN6/12/62

Set 5-5/8" casing at 2250', cemented with 1000 ex 6% reg with 1/4" P.S., 50-50 Pos Mix, Circulated.

8/29/62

Ran 243 jts. 7" casing 237-257 & 297, set at 10,100'. Cemented with 400 ex 50/50 3% joi, 200 50/50 Pos, 6% 1/4" P.S., 310 ex Incord, Mining Psi 2000, jumped to 7000, locked 15 ex having all mixed. Lost circulation. Had 70 bbls outside of pipe. Psi went up to 3700 at end.

8/30/62

Ran temperature survey, found T/Cement at 7500' (Welex). Perforated 2-1/2" holes at 7372', cemented with 200 ex 6% 1/4" P.S. and 200 reg. neat. Ran temperature survey. T/Cement at 6050'.

8/31/62

Worth Well ran temperature survey. Found T/Cement at 6370'. Plug at 7372'. Picked up 2-7/8" D.P.

9/1/62

Drilled T/Plug at 7372'. Found B/Plug at 9664'. Drid 416' of cement. Drid out to bottom but did not make new hole. Circ and cond mud.

9/2/62

Pulled out of hole. Picked up core barrel. Went in hole to core. Core No. 1 - Cut 20' highly fractured.

9/3/62

SET NO. 16 - Tested from 10,090' - 10,111'. Op one hr & 10 mins., weak blow, decreased and dead in one hr. Rec 1010' fluid, 270' drig mud & 740' S & W gas out. ISIP 3333, IFP 135 - III 4520, PSIP 2435, FFP 400 - III 4720

9/4/62

Welex set plug at 10,050'. Mandrei wouldn't release. Went in with D.P. and overshot. Got Mandrei. Welex set another plug at 10,035'. Went in with D.P. and sqd tool. Sqd W/50 ex at 5,1000.Psi. Started in formation at 4000, got 49 ex out. Left one sack in D.P.

9/5/62

Laid down D.P., rigged up Schlumberger. Logged well. Gas broke around, killed well with Halliburton truck.

9/6/62

Picked up 2-7/8" tbg. Went in hole open ended to circ gas out and condition mud. Mixing mud and weight material.

9/7/62

Pulled out of hole. Rigged up Western. Set Baker Model "W" Type "DM", magnesium cement retainer at 7332' (top of retainer). Sqd W/100 ex reg neat W/5000. Started in formation at 2-1/4 bbl per min. at 23500. Put away 25 ex. Circ. out 15 ex. Job complete at 11:00 C.S.T.

1 W
2 4
1 9 0