

January 26, 1956


Mr. Everett D. Burgett  
102 South Canal  
Carlsbad, New Mexico

Dear Sir:

Yes, it will be O.K. to plug the Malco-State No. 1 Well by filling the hole with pit mud & drill cuttings. Then set the regulation marker with the well number, quarter-quarter Section, Township and Range number stenciled thereon. Also file Form C-103 (in triplicate), Report of Plugging, along with Form C-105, Well Record, (6 copies).

Yours very truly,

OIL CONSERVATION COMMISSION

  
L. A. Hanson  
Supervisor, District No. 2

LAH/kw

## THE JOURNAL

OF THE  
ROYAL SOCIETY OF LONDON  
AND THE  
ROYAL SOCIETY OF MEDICINE

1881

THE JOURNAL OF THE ROYAL SOCIETY OF LONDON AND THE ROYAL SOCIETY OF MEDICINE, VOL. LXXV, PART I, 1881. LONDON: PUBLISHED BY THE SOCIETY, 1, ADELPHI WING, ST. MARTIN'S LANE. 1881.

PRINTED BY

JOHN BARNES, 1, ADELPHI WING, ST. MARTIN'S LANE.

1881

THE JOURNAL OF THE ROYAL SOCIETY OF LONDON AND THE ROYAL SOCIETY OF MEDICINE, VOL. LXXV, PART I, 1881.

1881