

915 N. Alameda St.  
Carlsbad, New Mexico  
April 5, 1958

New Mexico Oil Conservation Commission  
321 Carper Building  
Artesia, New Mexico

Dear Mr. Armstrong:

I would like to know if you have inspected the plugging job on my Binkley-Curry well, Sec 1, TS 21S, R27E, and whatever else should be done to bring into compliance with regulations so that I may be released from the one-well drilling bond. Mr. Binkley is at present in Carlsbad working for Joy Manufacturing and he can assist me in any way needed.

Thanks again for your consideration in this matter.

Sincerely,

  
Charles C. Curry

Charles C. Curry ,

There is junk on location. The hole that was spudded about 50' west of well has not been filled up, it is about 15' deep.

Oil Conservation Commission

April 26, 1958

I have worked this day to remove all junk from location and go fill up hole west of well, personally. Please advise if any other steps are necessary to secure release of bond.

