For 3160-5 (hovember 1983) Formerly 9-331)	EPARTMEN	D STATES DF THE INTER	OR verse side)	C. LEASE DESIGNATION AND SEGIAL NO. LC-063567			
SUNDR (Do not use this form Us	Y NOTICES A for proposals to drill "APPLICATION FOR	ND REPORTS (or to deepen or lug I PERMIT—" for each p	DNE WEVED BY Nack to a different reservoir. TOPOGRAM.	6. IP INDIAN, ALLOTTER OR TRIDE NAME			
I. OIL CAB WELL	OTHER WIW		JUN 00 1304	7. UNIT AGREEMENT NAME			
2. NAME OF OPERATOR			A DEFICE	8. FARM OR LEASE NAME			
Yates Energy Corporation			ARTESIA, OFFICE Yates Federal				
3. ADDRESS OF OPERATOR				9. WBLL NO.			
Sunwest Centre,	Suite 919, R	oswell, New Me	xico 88201	6			
 LOCATION OF WELL (Repor See also space 17 below.) At surface 	10. FIELD AND FOOL, OR WILDCAT MCMillan 7-Rivers Ouee 11. SEC., T., B., M., OR BLK. AND						
14 PERMIT S	990' FSL	Sec 6, $T-20S$, $R-27E$ 12. COUNTY OF PARISH 13. STATE					
· · · · · · · · · · · · · · · · · · ·		Eddy N.M.					
18 (Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO -			BUBBEQUENT REPORT OF :				
TEST WALLS BHIT-OFF	P111 PR 411	CER INSTRU	WATER SHUT-OFF	EFAIRING WELL			
FES T BE LEFAT	N 1 7140 8 0		FRACTUBE TREATMENT	ALTERING CASING			
$SH = T + \epsilon + 1012 h$	ABANGON	_ <u>X</u>	SECUTING OF ACIDIZING				
DEFAIR WF .	- HANGE FLA		(Other)				
(1*5e-			Nors Report results of multiple completion on Well Completion or Recompletion Report and Log form				
<pre>17 Less Fluids into constance(processor work of flowed) nect to this work of</pre>	PLETENSERATIONS () US Communication ally Carillee	budly state all pertinent L'give subsurface locat	details and give pertipent dat	es, including estimated date of starting a tical depths for all markets and some per			

6/5/84 As per our telephone conversation of this date, attached for your use as an aid to your understanding of our present predicament is a diagrammatic sketch of the injection set up and down hole tubular and packer originally submitted and followed in the original installation in 1970. This schematic may or may not be in your well file. Please disregard the steam injection line as this was not installed.

As per telephone conversation, June 4th, to state that we had a small pulling unit available to work on this well, on June 4th we entered the well and learned that the 2 3/8" tubing had rusted, corroded and parted. Present plugging material in the casing is at 141' from the surface. It appears to be scale, rust and debris. This well is no longer useful to us as an injector or a producer. We wish to abandon it.

In order to attempt to satisfy the requirements to adequately plug this well, we plan to move in a pulling unit and circulating-rotating equipment to "fish," mill and otherwise clean out the hole to prepare for abandonment by cementing same.

We request approval to place a 100' cement plug 50' below and above the 7" casing shoe at 422' (plug 472' to 372') and to install a regulation marker with 10 sxs of cmt at the surface.

1	I hereby certify that the foregoing is true and correct SHONED AND AND AND AND AND AND AND AND AND AN	John R. Mc	Minn, Engineer	DATEJune	5, 1984
	(The space for Federal or State office use)		<u> </u>		
	APPROVED BY CONTLICTS OF APPROVAL, IF ANY .	TITLE	<u>.</u>	DATE	

*See Instructions on Reverse Side