

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruction re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-063567

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates Federal

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

McMillan 7-Rivers Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 6, T-20S, R-27E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

Yates Energy Corporation

3. ADDRESS OF OPERATOR

Sunwest Centre, Suite 919, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below)
At surface

990' FSL & 330' FEL

14. PERMIT

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3371' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Revised request for approval to Plug to

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Abandon

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

6/11/84 TD 784'; 7" at 422' with 50 sxs cement. Water sands 50' to 60'; Water sands 320' to 335'. Top Seven Rivers 554'; top Queen 738'.
We plan to spot 200' plug 322' to 522'. Feel of top of plug. If not in place, respot and feel again. Displace with brine or mud. Leave brine or mud to surface. Perforate 7" casing at approximately 200' and circulate cement. Place regulation 4" pipe dry hole marker at surface.

what is this

18. I hereby certify that the foregoing is true and correct

SIGNED John R. McMinn

TITLE John R. McMinn, Engineer

DATE June 11, 1984

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side