

ARTESIA, NM 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN RIP
(Other instruction
vers. side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER WIW	5. LEASE DESIGNATION AND SERIAL NO. LC-063567
2. NAME OF OPERATOR Yates Energy Corporation ✓	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Sunwest Centre, Suite 919, Roswell, New Mexico 88201	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below) At surface 330' FSL & 330' FWL	8. FARM OR LEASE NAME Yates Federal
14. PERMIT NO.	9. WELL NO. 8
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3376' GR	10. FIELD AND POOL, OR WILDCAT McMillan 7-Rivers Queen
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 6, T-20S, R-27E
	12. COUNTY OR PARISH, 13. STATE Eddy N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WELL SHUT-OFF ☐ HILL OR ALTER CASING ☐
FRACTURE TREATMENT ☐ MULTIPLE COMPLETION ☐
SHOOTING OR ACIDIZING ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐

(Other) Revised request for approval to Plug to Abandon
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Include all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

6/11/84 TD 987'; 4 1/2" at 977' with 125 sx cement. Perforated 4 1/2" 879' - 891'.
Water sands 300' - 316'; Water sands 762' - 777'.
We plan to spot 200' plug 700' to 900', displace with brine water or mud. Feel top of plug, replace if not in place and feel again. Leave brine water or mud to surface. Perforate 4 1/2" at approximately 200'. Circulate cement.
Place regulation 4" pipe dry hole marker in cement at surface.

I hereby certify that the foregoing is true and correct

SIGNED John R. McMinn, Engineer DATE June 11, 1984

(This space for Federal or State office use)

APPROVED BY P. E. TITLE P. E. DATE 6/11/84

CONDITIONS OF APPROVAL, IF ANY.

*See Instructions on Reverse Side

RECEIVED BY
JUN 13 1984
O. C. D.
ADJUTANT GENERAL

RECEIVED
JUN 14 1984
O. C. D.
HOBBS OFFICE